

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Intense Type of Lease	
State ☒	Perm ☐
4. State Oil & Gas Lease No.	
LG-1397	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		7. Unit Agreement Name
2. Name of Operator Siete Oil and Gas Corporation		6. Perm or Lease Name Chaveroo State
3. Address of Operator Post Office Box 2523, Roswell, New Mexico 88201		8. Well No. 2
4. Location of Well NE 1/4 F 1980 North 2028 West LINE, SECTION 4 TOWNSHIP 8S RANGE 32E		10. Field and Pool, or Unit Chaveroo - San Andres
15. Elevation (Show whether DF, RT, CR, etc.) 4513 MSL		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 100a.

Will plug and abandon as soon as possible

100 foot plug on top of bridge plug at 4272' and tag

100 foot plug in and out of 4 1/4" casing at 3400' and tag

100 foot plug in and out of 8 5/8" casing at 1777' and tag

10 foot plug at surface with marker

Reference - Jerry Saxton on November 28, 1984 - verbal O.K. to plug and abandon

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed [Signature] TITLE President DATE November 28, 1984