FORM 3160-5

IITED STATES N.M. Oil S. Division PROVED DEPARTMENT OF THE INTERIOR 1625 N. Fre. . Sh Division No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS Do not use the term for topoposed of air or integers or eventy to a different reservoir. SUBMIT IN TRIPLICATE SUBMIT IN TRIPLICATE Type of Well Sort Gas Well Once Name of Operator CIRCLE RIDGE PRODUCTION, INC. Address and Telephone No. 1008 W. BROADWAY, HOBBS, NM 88240. 505-393-2727 Location of Well Foodage, Sec., T., R., M., or Survey Description) UNITE, SEC. 3, T13S, R31E 300 FNL & 1980 FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION Reserved Report Recomplished Subsequent Report Rescomplished Recomplished Recompli	(JUNE 1990)	BUREAU OF LAND MANAGEMEN	THomas NM 8824	Opires March 31, 1993	
SUBMIT IN TRIPLICATE			5. Lease	Designation and Serial No.	
SUBMIT IN TRIPLICATE Type of Well You well Gas Well Gas Well Other Name of Operator CIRCLE RIDGE PRODUCTION, INC. 30-005-2095 1008 W. BROADWAY. HOBBS, NM 88240 505-383-2727 10. Fels and Pool of Exploratory Area. CAPROCK QUEEN UNIT B, SEC. 3, T13S, R31E 300 FNL & 1980 FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intered New Construction Notice of Intered Abandoment Record Plugging Back New Construction Notice of Intered Recompletion Other Dispose Water Subsequent Report Dispose Water Final Abandoment Notice Consequent Operations (Cleanly state at particest details and give performed ideas, including estimated date of stating any spreaded work. If well is directionally distinct, give subsurface locations and measured and true vertical depths. For all marters and zones performed to this work.]* OB/08 & 06/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000-1800'. Tag cmt Liberative parts and the foregoing is true and correct Suprect Cappared for Folice and college of the well foregoing and the folice of the well foregoing and the folice of the well foregoing and the folice of the state of the well foregoing and the folice of the well fo	Do not u	se this form for proposals of drill or to deepen or reentry to a different			
Type of Well			7. If Unit	or CA, Agreement Designation	
TAO-FEDERAL #1 Name of Operator CIRCLE RIDGE PRODUCTION, INC. 9, APIWEI No. 1008 W. BROADWAY, HOBBS, NM 88240 505-393-2727 10, Field and Prod, or Exploratory Area. CAPROCK QUEEN 11, County or Parlate, State 11, County or Parlate, State 11,		SUBMIT IN TRIPLICATE			
Name of Operator CIRCLE RIDGE PRODUCTION, INC. Address and Telephone No. 1008 W. BROADWAY, HOBBS, NM 88240 595-393-2727 Location of Well (Foolage, Sec., T., R., M., or Survey Description) UNIT B, SEC. 3, T13S, R31E 330 FNL & 1980 FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent X. Abandosment Report Playing Back Recompletion New Construction New Co			8. Well N	Name and No.	
CIRCLE RIDGE PRODUCTION, INC. Address and Telephone No. 1008 W. BROADWAY, HOBBS, NM 88240 505-393-2727 Location of Well (Footage, Sec., T., R., M., or Survey Description) Location of Well (Footage, Sec., T., R., M., or Survey Description) LINIT B, SEC. 3, T1SS, R31E 307 FNL & 1980 FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandowment Recompletion Recompletion Recompletion Recompletion Recompletion Change of Plans Recompletion Recompletion Recompletion Recompletion Recompletion Recompletion Recompletion Recompletion Report Playing Back Conversion to Injection Disposed Water Recompletion (Clearly state all perfinent details and give perforent dates, including estimated date of stating and stating completion and measured and true vertical depths for all markers and course perforent bits work.) O6/08 & 06/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000'-1800'. Tag cmt ### 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. ABCT276d as to chicaging of the well Ress. Allaring caresty bond is rationed ungle #### Approved by 1000 Notify BLM. Date and correct Signed ##### Agent of Federal of Site office use) Date #### Date O6/13/100 **PETROLEUM ENGINEER** Date #### Date O6/13/100 **PETROLEUM ENGINEER** Date ##### Date O6/13/100 **PETROLEUM ENGINEER** **Date Office Note of Site office use) ###################################		Other	TAC)-FFDFRAL #1	
Address and Telephone No. 1008 W. BROADWAY, HOBBS, NM 88240 505-393-2727 Location of Well (Foolage, Sec. T., R., M., or Survey Description) UNIT B, SEC. 3, T13S, R31E 330' FNL & 1980' FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intert Notice of Intert New Construction New Construction to Injection Dispose Water Plugging Back Non-Routine Fracturing Dispose Water New Libert make an elimber of subscription to Injection Dispose water Plugging Back Non-Routine Fracturing Dispose Water New Construction to Injection Dispose water Plugging Back Non-Routine Fracturing Dispose Water New Construction to Injection Dispose water Plugging Back Non-Routine Fracturing setimated date of stating any proposed or Competition to Injection Dispose water Plugging Back Non-Routine Fracturing Dispose Water New Construction to Injection Dispose water Dispose Dispose Dispose Dispose Dispose Dispose Dispose Dispose Dispose Dispose	·				
1008 W. BROADWAY, HOBBS, NM 88240 505-393-2727 Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT B, SEC. 3, T13S, R31E 330 FNL & 1980 FEL CHAVES CO., N M CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent			9. API W	∕ell No.	
Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT B. SEC. 3, T13S, R31E 330 FNL & 1980 FEL CHAVES CO., N M CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent	Address and Telephone i	10.			
UNIT B. SEC. 3, T13S, R31E 330' FNL & 1980' FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Notice of I			10. Field	and Pool, or Exploratory Area	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent. Notice of Intent. Abandonment Change of Plans New Construction New Construction Notice of Intent. Abandonment Recompletion New Construction New Construction NoRoutine Fracturing Water Shut-Off Attering Casing Convestion to Injection Dispose Water Water Shut-Off Attering Casing Convestion to Injection Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Dispose Water Water Shut-Off Other Dispose Water Water Shut-Off Water Shut-Off Other Dispose Water Water Shut-Off Water Shut-Off Water Shut-Off Other Dispose Water Water Shut-Off Water Shut-Off Water Shut-Off Other Dispose Water Water Shut-Off Water Shut-Off Water Shut-Off Water Shut-Off Other Dispose Water Water Shut-Off Water Shut	Location of Well (Footage	, Sec., 1., K., W., of Survey Description,	C	APROCK QUEEN	
CHAVES CO., N.M. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion New Construction New Construct	•		11. Coun	ty or Parish, State	
TYPE OF SUBMISSION TYPE OF ACTION Notice of Inlant	330' FNL & 1980' FE	-			
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent			CI	HAVES CO., NM	
Notice of Intent X Abandonment Change of Plans New Construction Plugging Back Non-Routine Fracturing Water Shut-Off Altering Casing Repair Water Shut-Off Dispose Water Conversion to Injection Dispose Water	CHECK APPROP	RIATE BOX(s) TO INDICATE NATURE OF	NOTICE, REPORT, OR	OTHER DATA	
Recompletion New Construction New Construction	TYPE OF SUBMISSION	TYF	TYPE OF ACTION		
Recompletion New Construction New Construction New Construction Non-Routine Fracturing Plugging Back Non-Routine Fracturing Water Shut-Off Attering Casing Conversion to Injection Dissoner to Injection Other Dissoner to Injection	Notice of Intent	X Abandonment	Chan	nge of Plans	
Plugging Back Non-Routine Fracturing Water Shut-Off Altering Casing Repair Water Shut-Off Other Dispose Water (Note: Report results of multiple completion on Well Completion of multiple completion on Well Completion of Recompletion Report and Log Form). O6/08 & 06/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000'-1800'. Tag cmt @ 1694'. Perf @ 616'. RIH w/pkr to 400' & sqz 35 sxs cmt WOC. Tag @ 512'. Spot 25 sxs @ 512' & 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. Approved by Pic Septiment of Date of Recompleted. Agent Date Date Date of Recompleted. PETROLEUM ENGINEER Oct 18 2		Recompletion	New	Construction	
Altering Casing Conversion to Injection Dispose Water Place Report media of multiple completion on Wall Completion of Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* O6/08 & O6/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000'-1800'. Tag cmt @ 1694'. Perf @ 616'. RIH w/pkr to 400' & sqz 35 sxs cmt WOC. Tag @ 512'. Spot 25 sxs @ 512' & 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. Approved as to placeting of the well lines. Approved by PIC ORD DAVID S. CLASS Title PETROLEUM ENGINEER Date 08/3 1/0 0 OCT 18 2	X Subsequent Report	Plugging Back	Non-	Routine Fracturing	
Dispose Water Notes Report results of multiple completion on Well Completion of Paccompletion on Well Completion of Paccompletion Report and Log Form). 3. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) O6/08 & 06/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000'-1800'. Tag cmt @ 1694'. Perf @ 616'. RIH w/pkr to 400' & sqz 35 sxs cmt WOC. Tag @ 512'. Spot 25 sxs @ 512' & 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. Approved as to plugging of the well form. Approved by PIC SUD DAVID F. CLASS Title PAGENTY Date OBS NATION ON THE COLOR OF TITLE OF TROLEUM ENGINEER Date OBS/31/00 OCT 18 2	Final Abandoment Notice	Casing Repair	☐ Wate	er Shut-Off	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form) 3. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. It well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* O6/08 & O6/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000'-1800'. Tag cmt @ 1694'. Perf @ 616'. RIH w/pkr to 400' & sqz 35 sxs cmt WOC. Tag @ 512'. Spot 25 sxs @ 512' & 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. Approved as to plugging of the well licentary bond is retained until attributed resources for Federal or State office use) Approved by PIC OBD DAND F. CLASS Title O27 18 2		Altering Casing	Conv	version to Injection	
3. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) O6/08 & O6/09/00 Notify BLM, MIRU. POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP @ 2900'. Circ 10# mud to surf. Spot 15 sxs cmt on top CIBP. Spot 30 sxs @ 2000'-1800'. Tag cmt @ 1694'. Perf @ 616'. RIH w/pkr to 400' & sqz 35 sxs cmt WOC. Tag @ 512'. Spot 25 sxs @ 512' & 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. Approved as to plugging of the well form. Approved as to plugging of the well form. All hereby certify that the foreoging is true and correct Signed Approved by: Title AGENT Date 0.8/3.1/0.0 Title AGENT Date 0.8/3.1/0.0 Date 0.8/3.1/0.0		Other			
16. I hereby certify that the foregoing is true and correct Signed Markers and zones perment to this work. Title AGENT Trite AGENT Trite AGENT Trite POOH w/118 rods, NU BOP. POOH w/92 jts tbg. Set CIBP To all markers and zones perment to this work. This work. To all markers and zones perment to this work. This work work and zones perment to this work. This work work and zones perment to this work. This work work and zones perment to this work. This work work and zones perment to this work. This work is retained unit work. This work is retained unit work and zones perment to this work. This work work and zones perment to this work. This work work and zones perment to this work. This work is retained unit work and zones perment to this work. This work is retained unit work and zones perment to this work. This work is retained unit work and zones perment to this work. This work is retained unit work and zones perment to this work. This work is a perment to this work. This work is the foregoing is true and correct. Approved by PIC GODY DAND S. GLASS Trite Pool and zones perment to this work. This work is the foregoing is true and correct. Approved by PIC GODY DAND S. GLASS Trite Pool and zones perment to this work. This work is the foregoing is true and correct. Approved by PIC GODY DAND S. GLASS Trite Pool and zones perment to this work. This work is the foregoing is true and correct. Approved by PIC GODY DAND S. GLASS Trite Pool and zones perment to this work is the foregoing is true and zones. This work is the foregoing is true and zones perment to this work is the foregoing is true and zones. This work is the foregoing is true and zones perment to this work is the foregoing is true and zones perment to this work is the foregoing is true and zones perment to the foregoing is the perment to this work is the foregoing is the perment to the foregoing is the perment to the foregoing is the perment to the perme			Comple	etion or Recompletion Report and Log Form).	
@ 1694'. Perf @ 616'. RIH w/pkr to 400' & sqz 35 sxs cmt WOC. Tag @ 512'. Spot 25 sxs @ 512' & 10 sxs @ 90' to surf. cut off wellhead. Level pit & cellar. Install Dry Hole Marker. Approved as to plugging of the well tability under bond is retained until attribute reasonation in completed. 4. I hereby certify that the foregoing is true and correct Signed County Hole Marker. Date 0 8/3 1/0 0 Approved by FIG OUD 1 DAVID F. CLASS Title PETROLEUM ENGINEER Date 0CT 18 2	o6/08 & 06/09/00	ive subsurface locations and measured and true vertical depths for a Notify BLM, MIRU. POOH w/118 rods, NU	BOP. POOH w/92 jts tbg.	. Set CIBP	
Approved as to plugging of the well flow. Liability under bond is retained until aurises restoration is completed. 4. I hereby certify that the foregoing is true and correct Signed	@ 2900'. Circ 10#	mud to surf. Spot 15 sxs cmt on top CIBP.	Spot 30 sxs @ 2000'-180	JU'. Tag cmt	
Approved as to plugging of the well from Liability under bond is retained until auritace restoration in completed. 4.1 hereby certify that the foregoing is true and correct Signed Hough Hord Title AGENT Date 08/31/00 This space for Federal or State office use) Approved by FIG ORD DAVID F. GLASS Title Date 0CT 18 2	@ 1694'. Perf @ 6	616'. RIH w/pkr to 400' & sqz 35 sxs cmt WC	OC. Tag @ 512'. Spot 25	sxs @ 512' &	
Auritace restoration in completed. A	10 sxs @ 90' to su	f. cut off wellhead. Level pit & cellar. Insta	ıll Dry Hole Marker.	ALDER S	
Signed Coupe Act of Title AGENT Date 08/31/00 This space for Federal or State office use) Approved by FIG OUD DAVID F. CLASS Title PETROLEUM ENGINEER Date 08/31/00			William Cond in recolerate and	vell licen. ridi	
This space for Federal or State office use) Approved by SEC OCO DAVID F. CLASS Title PETROLEUM ENGINEER Date OCT 18 2	14. I hereby certify that the foregoin	g is true and correct			
Approved by PIG ORD DAVID F. CLASS Title PETROLEUM ENGINEER Date OCT 18 2	signed Boure Al	ard Title AGENT		Date 08/31/00	
Approved by Table 1100	• •		im enginees	ብ ስ ፕ 1 o 2	
	· · · · · · · · · · · · · · · · · · ·	DAVID SULLAND Title	UM ENUINEEN	Date ULI 18 Z	