

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-20968
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. V-861
7. Lease Name or Unit Agreement Name Bunker Hill State
8. Well No. 1
9. Pool name or Wildcat (Gas) Anderson Ranch <i>Perm</i> West
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4393 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. Name of Operator National Energy Group, Inc.
3. Address of Operator 4925 Greenville Ave., #1400 Dallas, TX 75206	4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>south</u> Line and <u>660</u> Feet From The <u>east</u> Line Section <u>33</u> Township <u>15-S</u> Range <u>31-E</u> NMPM <u>Chaves</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4393 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/14/95 1) Set 5½" CIBP @ 12,003' & capped w/ 25 sxs cmt.
3/14/95 2) Circ hole w/ 10# brine w/ 25# salt gel per barrel.
3/15/95 3) Spot 25 sxs plug from 10,312'-9959'.
3/15/95 4) Spot 25 sxs plug from 7102'-6849'.
3/15/95 5) Spot 25 sxs plug from 4118'-3865'.
3/15/95 6) Perf 5½" & 9-5/8" csg @ 420'. Pump 50 sxs cmt & displace TOC to 275'. WOC
3/16/95 7) Tag plug @ 270'.
3/16/95 8) Spot 10 sxs plug 54'-4'.
3/16/95 9) Cut off W.H. & install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joey D. Fields TITLE Agent DATE 3/17/95

TYPE OR PRINT NAME Joey D. Fields TELEPHONE NO. (915) 688-0160

(This space for State Use)

APPROVED BY Billy E. Prichard TITLE Field Rep DATE NOV 04 1995

CONDITIONS OF APPROVAL, IF ANY: