

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240

Budget Bureau No. 1604-  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 22637

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Pearson-Sibert Oil Co. of Texas	8. FARM OR LEASE NAME R-V-S.-Federal RVS
3. ADDRESS OF OPERATOR 901 W. Missouri Avenue, Midland, Texas 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FN&EL's Section 27, T-10-S, R-30-E	10. FIELD AND POOL OR WILDCAT Wildcat
14. PERMIT NO. Permit dated 9-20-84	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T-10-S, R-30-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4093' GR	12. COUNTY OR PARISH Chaves
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Well dry and abandoned 12-7-84.

12-5-84:

Pulled 77 jts. (2810') 5-1/2" 15.5# ST&C casing. Casing left in well: 13-3/8" 48# @ 32'; 8-5/8" 24# @ 345' and 5-1/2" 15.5# @ 990'.

12-7-84:

Set cement retainer @ 3535'. Casing Perforations 3574' to 3749' squeezed with 200 sacks. 5-1/2" casing stub @ 2810'. 50-sack plug @ 576'. 100-sack plug @ 379' to 276'. 10-sack plug @ surface. 8-5/8" casing shoe @ 345'. Set dry hole marker.

12-20-84:

Location cleaned of trash and equipment.

5-85:

Dug pits to bury mud and caliche. Covered caliche pad. Ripped up road and sowed grass seed. Surface restoration completed 5-19-85.

18. I hereby certify that the foregoing is true and correct

SIGNED Robert D. Little

TITLE Vice President

DATE 4-14-86

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

APPROVED  
DATE  
PETER W. CHESTER

JAN 30 1987

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

\*See Instructions on Reverse Side