

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Company	8. Farm or Lease Name New Mexico "BA" State
3. Address of Operator P.O. Box 1861 Midland, Texas 79702	9. Well No. 4
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>8S</u> RANGE <u>31E</u> NMPM.	10. Field and Pool, or Wildcat Siete San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4233	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER Additional work done after potential test. ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4/29/85 MIRU DA&S. POH w/rods & pump. NU BOP POH w/2-3/8" tbg. TIH w/5-1/2 RDG pkr on 2-3/8 tbg to 3700'. SDFN
- 4/30/85 Lwr pkr to 3784' Howco spot 2 bbls 20% NEFE HCL acid from 3784' to 3700'. Set pkr @ 3607'. Press annulus to 1000#, Howco acidize. SA Set I & II 3740-84 w/5000 gals 20% NEFE HCL acid.
- 5/1/85 TIH w/2-3/8 tbg & pumping set up. TS 3794' SN 3784' ND BOP. NU Wellhead. RIH w/2 x 1-1/2 x 16 pump on 66 rod string spaced out. Hang on. RR
- 5/14/85 MIRU RAM W.S./POH w/rods & pump, NU BOP, POH w/2-3/8 pumping setup McCabe W.L. P.B. w/sd 3830-3772/SDFN/
- 5/15/85 Strap in hole to 3604 w/5-1/2 RDG pkr on 2-3/8 tbg. Set pkr. Press annulus to 500#. Western frac SA perfs 3740-72 w/16,000 gals Apollo 40 + 29,000# 20/40 sd.

(SEE ATTACHED SHEET ADDITIONAL INFORMATION)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Velma Reyes TITLE Sr. Accounting Assistant DATE 5/30/85

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN - 3 1985

CONDITIONS OF APPROVAL, IF ANY:

1931 1935

Page 2  
Velma Reyes

NEW MEXICO "BA" STATE #4  
CHAVES COUNTY

- 5/16/85 21 hr SITP 0, Rel pkr, Lwr & tagged Sd @ 3750 POH/RIH w/Bulldog bailer on 2-3/8 tbg, cleaned out Sd. 3750-3770, Bailer failed, POH & Rec 20 gal Sd/SDFN
- 5/17/85 RIH w/3" Bulldog bailer on 2-3/8 tbg, tag Sd @ 3770, Cln out to 3830 PBD, Pull up 60' & wait 3/4 hr, lower to 3830, had no fill/POH & rec 35 gals sd & 10 ball sealers/RIH w/2-3/8 pumping setup, TS 3667, SN 3657, Remove BOP, NU wellhead, RIH w/1-1/2 pump & rods, spaced out, hung on/RR/

1985  
JAN 21 1985  
ACD