

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-21038
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-8250

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Enstar ACW State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 1
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	9. Pool name or Wildcat Undesignated San Andres
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>8S</u> Range <u>33E</u> NMPM <u>Chaves</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4356' GR	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
2-14-95 - Moved in and rigged up pulling unit. POOH with rods and tubing. Rigged up wireline. TIH with 5-1/2" CIBP and set at 3450'. Capped CIBP with 35' of cement. Rigged down wireline. RIH with tubing. Shut down.  
2-15-95 - Circulated hole with mud. POOH with tubing to 3950'. Spotted a 35 sack cement plug. POOH and laid down extra tubing. Nippled down wellhead. Weld on to 5-1/2" casing. Took casing stretch - free at 2000'. Rigged up wireline and 5-1/2" cutter. TIH with cutter and cut casing at 2000'. Rigged down wireline. Rigged up casing tongs. Shut down.  
2-16-95 - POOH with 48 joints of 5-1/2" casing. TIH with tubing to 2050'. Spot a 35 sack cement plug on 5-1/2" stub. POOH. WOC 3 hours. TIH with tubing and tag top of cement at 1948'. Spotted a 35 sack cement plug across 13-3/8" casing shoe at 360'. POOH with tubing. Spot a 10 sack cement plug at surface. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 2-15-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 3-1-95  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY Billy E. Prueher TITLE  DATE

**RECEIVED**

MAR 03 1995  
UNITED STATES  
OFFICE