

# OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-005-21046

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG-1348

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☐

GAS WELL ☐

OTHER P & A

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter E : 1650 Feet From The North Line and 330 Feet From The West Line

Section 22

Township 8S

Range 33E

NMPM

Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4368.1' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-7-95 - Moved in and rigged up pulling unit. Nippled down horses head. POOH with rods and tubing. Shut down for night.

2-8-95 - Rigged up wireline. TIH with 5-1/2" CIBP and set at 4250' and capped with 35' of cement. Rigged down wireline. TIH with tubing. Loaded hole with mud. TOOH with tubing. Nippled down wellhead. Rigged up casing equipment. Pulled wellhead slips. Took casing stretch on 5-1/2" - shows free at 3000'. Rigged up wireline and casing cutter. RIH and cut casing at 3016'. POOH with 5 joints of casing. Shut down for night.

2-9-95 - TOOH with remainder of 5-1/2" casing (total of 75 joints). Rigged down casing equipment. Rigged up tubing equipment. TIH with tubing to 3066'. Spot a 30 sack cement plug across 5-1/2" stub. WOC. TIH with tubing and tag top of cement at 2940'. TOOH

with tubing to 1956'. Spotted a 40 sack cement plug across 8-5/8" casing shoe. WOC. 2-10-95 - TIH with tubing. Tagged top of cement at 1838'. POOH and laid down tubing. Spotted a 10 sack cement plug at surface. Installed regulation abandonment marker.

PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 2-9-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Rusty Klein*

TITLE Production Clerk

DATE 2-17-95

TYPE OR PRINT NAME

Rusty Klein

505-748-1471  
TELEPHONE NO.

(This space for State Use)

APPROVED BY

*Billy E. Puchner*

TITLE

DATE

*N* *Br*