SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for groupout to deepen or gring back to a different reservoir. OIL		N. M. OIL CONS. CONNIS.) STATES	SUBMIT IN TRIPLIC. A	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (the not use this form for proposed to state of the product	Formerly 9-33	HODES NEW MEXICO ISSUE MANAGEMEN	T	
(Do not use Table from for proposals to defill or to decepts or place back to a different reservoir. Out Out				6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OUL	(Ďo not s	able from for proposale to delli or to deepen or ping	back to a different reservoir.	
Experience of control of the property of the p				7. UNIT AGREEMENT NAME
3. ADDRESS OF STEELENS OF ACTION OF				8. FARM OR LEASE NAME
4. Decarion of all Report locations clearly and in accordance with any State requirements.* Security Process of PNIL & 1980' FWIL 11. FRENIT NO. 12. CORRECT ON DATE: A017.7 14. FRENIT NO. 15. SECURITY ON ASSETTION AND STATE OF ALL STATES OF ALL STA				Cheyron 18 Federal 9. WBLL NO.
See also space IT New York State and Control of Check Appropriate Box To Indicate Notice of Notice, Report, or Other Data State State Notice or interior to 1. 16. Check Appropriate Box To Indicate Notice of Notice, Report, or Other Data State State Notice or interior to 2. 17. The Notice or interior to 2. 18. Check Appropriate Box To Indicate Notice of Notice, Report, or Other Data State State Notice or interior to 2. 18. Check Appropriate Box To Indicate Notice of Notice, Report, or Other Data State State Notice or interior to 2. 18. Check Appropriate State Notice or interior to 2. 18. Check Appropriate State Notice or interior to 2. 18. Check Appropriate State Notice or interior to 2. 18. Check Appropriate State Notice or interior to 2. 18. Check Appropriate State Notice or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Approved State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate State Notice Or interior to 2. 18. Check Appropriate Or Approval. If Ann. Check	P.O. Bo:	x 1933 Roswell, N.M. 88201		11
At surface 660' FNL & 1980' FWL Caro-San Andres Caro-San Andr	See also space	e 17 below.)	10. FIELD AND POOL, OR WILDCAT	
11. ELEVATION (Show whether or, st. cs. etc.) 12. COUNTY OR PARISH 18. STATE 13. Chayes NM 14. Chayes NM 15. Chayes NM 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INVENTION TO: TEST WATER SHOT-OFF PELL OR ALTER CISINO PARCTURE TREAT ALTERING CASINO ALRANOSH PERSON SHOOT OR ALCIDIER ALTERING CASINO ALTERING CASINO ALRANOSH PELL (Other) Chayes Report results of multiple completion on Well (Note: Report results of multiple completion on We	At surface	660' FNL & 1980' FWL		11. SEC., T., R., M., OR BLK. AND
18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data **Notice of Intention to:** **TEST WATER SHICTOFF*** **PACTURE TREAT*** **SHOOT ON ACTION TO ALTER CASING** **PACTURE TREAT*** **ALTER WALL** **GOLDEN*** **CHANGE PLANS** **CHANGE PLANS** **CHANGE PLANS** **COLUMN TO ACTION TO ALTER CASING OF ALTER CASING	14 PERMIT NO.	i 15. ELEVATIONS (Show whether D	F, RT. GR. etc.)	Sec-18 T-9S R-30E 12. COUNTY OR PARISH 13. STATE
Check Appropriate Box To Indicate Notice, Report, or Other Data Notice of Intention to: ***TEST WATER BRUT-OFF*** ***PILL OR ALTER CASINO*** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING OR ACIDIZE** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING OR ACIDIZE** ***PILL OR ALTERING OR ACIDIZE** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING OR ACIDIZE** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING OR ACIDIZE** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING CASINO*** ***PILL OR ALTERING CASINO*** ***PACTURE TREATMENT*** *	11, 130,012		.,,	Charre - ND4
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIEN MATCHIES CRAINS MAT				
TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIES SHOOT	16.	Check Appropriate Box To Indicate I	• • •	
PRACTURE TREAT SHOOT OR ACIDIZE SEPARE WELL CHANGE PLANE CHANE CHANGE PLANE CHANGE		NOTICE OF INTENTION TO:	SUBSEC	QUENT REPORT OF:
ABANDON & ACIDIZE REPAIR WELL (Other) CHANGE PLANS CONDITIONS OF APPROVAL, IF ANY: APPROVED PLANS CHANGE PLANS	TEST WATER	SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
nepair well (Other) Other) O	FRACTURE TE	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
(Other) (Nors: Report results of multiple completion on Well (Completion or Recompletion or Recompletion or Recompletion or Recompletion for and Completion for all directionally drilled. give subsurface locations and measured and true vertical depths for all markers and sones near to this work.] 2-22-86 Perforate 4 holes @ 3328 & acidize w/ 750 Gal 15%-Swab Test 2-25-86 Set CIBP @ 3324. Perforate 4 holes @ 3307 & acidize w/ 750 Gal 15% & Swab Test. 3-1-86 Perforate 4 holes @ 3295 & acidize w/ 750 Gal 15%. Swab Test. 3-5-86 Acidize w/ 3000 Gal 15% & BAF - Swab Test. 3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18.1 hereby certify that the foregoing is true and correct SIGNED Market Depth of the well bore. Liability under bond is retained until	SHOOT OR AC	IDIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* X
17. DESCRIBE PROPOSED ON COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent address, localiding estimated date of starting nent to this work.). 2-22-86 Perforate 4 holes @ 3328 & acidize w/ 750 Gal 15%-Swab Test 2-25-86 Set CIBP @ 3324. Perforate 4 holes @ 3307 & acidize w/ 750 Gal 15% & Swab Test. 3-1-86 Perforate 4 holes @ 3295 & acidize w/ 750 Gal 15%. Swab Test. 3-5-86 Acidize w/ 3000 Gal 15% & BAF - Swab Test. 3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker - P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct SIGNED Approved as to plugging of the well bore. Chability under bond is retained until		CHANGE PLANS		as of multiple completion on Well
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones nent to this work.)* 2-22-86 Perforate 4 holes @ 3328 & acidize w/ 750 Gal 15%-Swab Test 2-25-86 Set CIBP @ 3324. Perforate 4 holes @ 3307 & acidize w/ 750 Gal 15% & Swab Test. 3-1-86 Perforate 4 holes @ 3295 & acidize w/ 750 Gal 15%. Swab Test. 3-5-86 Acidize w/ 3000 Gal 15% & BAF - Swab Test. 3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker - P&A @ 12:05 PM 3-15-86 18. Thereby certify that the foregoing is true and correct signed. (This space for Federal or State office use) Approved as to plugging of the well bore. Liability under bond is retained until			Completion or Recom	pletion Report and Log form.)
2-25-86 Set CIBP @ 3324. Perforate 4 holes @ 3307 & acidize w/ 750 Gal 15% & Swab Test. 3-1-86 Perforate 4 holes @ 3295 & acidize w/ 750 Gal 15%. Swab Test. 3-5-86 Acidize w/ 3000 Gal 15% & BAF - Swab Test. 3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certity that the/foregoing is true and correct Signed W N.M. Young Title Drilling Superintendent DATE (This space for Federal or State office use) Approved as to plugging of the well bore. Liability under bond is retained until	proposed w	vork. If well is directionally drilled, give subsurface local	ations and measured and true verti	cal depths for all markers and sones perti-
A Swab Test. 3-1-86 Perforate 4 holes @ 3295 & acidize w/ 750 Gal 15%. Swab Test. 3-5-86 Acidize w/ 3000 Gal 15% & BAF - Swab Test. 3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the/toregoing is true and correct SiGNED N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) Approved as to plugging of the well bore. Liability under bond is retained until	2-22-86	Perforate 4 holes @ 3328 & acidi	ze w/ 750 Gal 15%-Swa	ab Test
3-5-86 Acidize w/ 3000 Gal 15% & BAF - Swab Test. 3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct SIGNED N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) Approved BY CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	2-25-86			
3-7-86 Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test. 3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct Signed N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) Approved by CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	3-1-86	Perforate 4 holes @ 3295 & acidize w/ 750 Gal 15%. Swab Test.		
3-12-86 Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test. 3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct SIGNED N.M. Young TITLE Drilling Superintendent (This space for Federal or State office use) Approved by CONDITIONS OF APPROVAL, IF ANY: CONDITIONS OF APPROVAL, IF ANY: Liability under bond is retained until	3-5-86	Acidize w/ 3000 Gal 15% & BAF - Swab Test.		
3-14-86 Set CIBP @ 3230 & put 35' cement on top. cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct SIGNED N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	3-7-86	Perforate 4 holes @ 3265 & acidize w/ 450 Gal 15%-Swab Test.		
cut off 5 1/2" csg @ 2640. 3-15-86 Set 30sk plug from 2720 to 2570 Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct SIGNED N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) Approved by CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	3-12-86	Perforate 4 holes @ 3248 & acidize w/ 750 Gal 15%-Swab Test.		
Set 50sk plug from 933 to 783 Set 10sk plug @ surface Install dry hole marker- P&A @ 12:05 PM 3-15-86 18. I hereby certify that the foregoing is true and correct SIGNED N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	3-14-86			
N.M. Young TITLE Drilling Superintendent DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	3-15-86	Set 50sk plug from 933 to 783 Set 10sk plug @ surface		
(This space for Federal or State office use) APPROVED BY	18. I hereby cert	ify, that, the foregoing is true and correct		
APPROVED BY APPROVED APPROVED APPROVED APPROVED APPROVED	signed	N.M. Young TITLE D	rilling Superintender	nt DATE
APPROVED BY CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore. Liability under bond is retained until	(This space f	or Federal or State office use)		ADDROVED
Approved as to plugging of the well bore. Liability under bond is retained until	APPROVED	BY TITLE		APPROVED I
		Approved as to pluggin Liability under bond is surface restoration is c	retained until completed.	·
DOGWELL RESOURCE THE	Title 13 U.S.C.		•	BUREAU OF LAND MANAGEMENT an ROSWELL RESOURCE AREA

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

State or Federal office for specific instructions Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

PRIVACY ACT

The Privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et. seq., 351 et. seq., 25 U.S.C. et. seq.; 43 CFR 3160. PRINCIPAL PURPOSE: The information is to be used to evaluate, when appropriate, approve applications, and report completion of secondary well operations, on a Federal or Indian lease.

ROUTINE USES: (1) Evaluate the equipment and procedures used during the proposed or completed subsequent well operations. (2) Request and grant approval to perform those actions covered by 43 CFR 3162.3-2(2). (3) Analyze future applications to drill or modify operations in light of data obtained and methods used. (4)(5) Information from the record and or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions.

EFFECT OF NOT PROVIDING INFORMATION: Filing of this notice and report and disclosure of the information is mandatory once an oil or gas well is drilled.

The Paperwork Reduction Act of 1980 (44 U.S.C. 3501, et. seq.) requires us to inform you that:

This information is being collected in order to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

This information will be used to report subsequent operations once work is completed and when requested, to obtain approval for subsequent operations not previously authorized.

Response to this request is mandatory for the specific types of activities specified in 43 CFR Part 3160.