


Diagram to Plug and Abandon



RECEIVED
MAY 27 1987
OCD
HOBBS OFFICE