

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

FLYING WV #1
Unit A, Section 34, T8S-R33E
Chaves County, New Mexico

DRILL STEM TEST

DST #1 8462-8587' (125') ABO: TO 30"; SI 80"; TO 60"; SI 180".
Opened on bubble hole with weak blow (1'), decreased to 1/2" in 10
minutes and dead in 20 minutes. SI. Opened with no blow. SAMPLER:
.06 cfg, 900 cc mud with 30# pressure. RECOVERY: 40' mud. PRESSURES:
IHP 4624, IFP 122-122, ISIP 162, FFP 130-137, FSIP 167, FHP 4611.