

UNITED STATES N. M. OIL CONS. COMMISSION
DEPARTMENT OF THE INTERIOR BOX 1980
BUREAU OF LAND MANAGEMENT HOBBS, NEW MEXICO 88240

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Dakota Resources, Inc. (I)	8. FARM OR LEASE NAME STARSHOOTER Federal
3. ADDRESS OF OPERATOR 310 W. WALL, Ste. 415 Midland, TX. 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FWL & 660' FNL Sec. 18, T13S, R31E	10. FIELD AND POOL, OR WILDCAT Southway Chavez CABROCK Queen H. Area
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	12. COUNTY OR PARISH CHAVES
13. STATE N.M.	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 400' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☒	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- (8-27-90) Rig Up Well Ser. Unit. 100psi on hbg. Swab Well Dry. No Show
- (8-28-90) FRAC Well w/ 9200GAL X-Linked gel + 10.6*/GAL. 12-20 SAND & 17 TONS CO₂.
Open Well up & BLEED Press. Down. No Shows.
- (8-29-90) Rig up SWAB. IFL @ 1009' - Swab 8 Hrs. Recovered 10 bbls. Load wtr
No Gas. Rig Pulling Unit Down.
- (9-6-90) Rig up Well Ser. Unit. SITP = 50 PSI. IFL @ 1800' FS. SWABbed
& Recovered 6 Bbls. wtr. Gas - TSTM.
- (9-7-90) SITP = 25 PSI. IFL @ 1600 PSI. SWABbed & Recovered 4 bbls. wtr.
No Shows. *

* Note: Will Request Plugging Instructions from BLM.

18. I hereby certify that the foregoing is true and correct

SIGNED

Chris M. Morgan

TITLE

President

DATE

9-12-90

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

ACCEPTED FOR RECORD
PETER W. CHESTER

OCT 5 1990

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED
OCT 10 1967
U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION