

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-21138
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-1398-2
7. Lease Name or Unit Agreement Name "SV" Vest State
8. Well No. 1
9. Pool name or Wildcat Vest Ranch-Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3856' GL

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Manzano Oil Corporation 505/623-1996

3. Address of Operator  
P.O. Box 2107/Roswell, NM 88202-2107

4. Well Location  
Unit Letter N : 330 Feet From The South Line and 1650 Feet From The West Line  
Section 16 Township 14 South Range 30 East NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/17/00 Notify OCD. MIRU. LD rods. Nipple up BOP. Close in well.  
 4/18/00 Circl 10# mud. POOH w/100 jts tbg. Stretch csg. Cut csg @ 2894'. LD 69-1/2 jts. Close in well.  
 4/19/00 RIH w/tbg to 2966'. Circl 10# mud. Spot 50 sks @ 2966'. POOH. WOC. RIH & tag @ 2793'. POOH & spot 35 sks @ 1120-986'. POOH and spot 50 sks @ 396'. POOH. Will tag in a.m.  
 4/20/00 RIH & tag cement @ 203'. POOH & spot 10 sks @ surface. Cut off wellhead. Level pit & cellar. Install dry hole marker. Move out.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Hernandez TITLE Engineering Technician DATE 5/8/00  
 TYPE OR PRINT NAME Allison Hernandez TELEPHONE NO. 623-1996

(This space for State Use)

APPROVED BY [Signature] TITLE F.W. Rep DATE 1-30-01  
 CONDITIONS OF APPROVAL, IF ANY:

MCD