

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-00210</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <u>Resistal #</u>
2. Name of Operator <u>J & G Enterprise Ltd Co.</u>	8. Well No. <u># 1</u>
3. Address of Operator <u>Po Box 100, Artesia, NM 88210</u>	9. Pool name or Wildcat <u>wildcat Morrow</u>
4. Well Location Unit Letter <u>C</u> : <u>652.94'</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>13 S</u> Range <u>32 E</u> NMPM <u>Lea</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Reentry</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-16-97 MI, RU pulling unit. Drill surface, plug & plugs to 1046'. Ran 8 5/8" casing and tie to 8 5/8" cut off- Drill plugs and clean out to 11,278', POH, ran 4 1/2 N-80, LT&C 8 rd casing w/ float shoe & float collar to 11,253'- 255 jts. Cement with 650 sks 50-50 Posmix w/290 gel, 4% salt, .005% of FL 15 2 - 1/4#. Celloplate- WOC

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J T Jackson TITLE President DATE 7-11-97
TYPE OR PRINT NAME J T Jackson TELEPHONE NO. 505-746-968

(This space for State Use) ORIGINAL SIGNED BY GARY WINK
FIELD REP. II
APPROVED BY _____ TITLE _____ DATE APR 06 1998
CONDITIONS OF APPROVAL, IF ANY:

010102
7/10/97
#0