

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

tional instructions in the Rules and Regular	Indicate Nature of Notice by C	hecking Bel	ow	
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner	xx
Notice of Intention to Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	Breckenridge,	Texas		r 4, 1956
Gentlemen:	(Place)		(Date)	
Following is a Notice of Intention to d Graridge Corporation NW NE (Company or Operator) 1/4 of Sec	o certain work as described below as Manry-State "A"	the	W.H.N. 2	В
NW NE (Company or Operator	_ 13 32		Canrock 2	(Unit)
	, T, R	,NMPM.,		Po
(FOLLOW Clean out well and run G		etermin	egulations)	
Clean out well and run G Plug back to top of sand Drill out cement, clean	amma-Ray Survey to d and cement 5-1/2" line out, and put on product	etermin	egulations)	
Clean out well and run G Plug back to top of sand Drill out cement, clean of	amma-Ray Survey to d and cement 5-1/2" line out, and put on product	etermin	esculations) estop of sand. of sand.	
Clean out well and run G Plug back to top of sand Drill out cement, clean of sand Approved	amma-Ray Survey to d and cement 5-1/2" line out, and put on product	etermin	egulations)	
Clean out well and run G Plug back to top of sand Drill out cement, clean of sand Approved	amma-Ray Survey to deand cement 5-1/2" line out, and put on product	eterminer at top	e top of sand. of sand. ige Corporation Company or Operator	tendent
Clean out well and run G Plug back to top of sand Drill out cement, clean of sand Approved	amma-Ray Survey to d and cement 5-1/2" line out, and put on product	etermin or at top ion.	esculations) setop of sand. of sand.	· · · · · · · · · · · · · · · · · · ·
Clean out well and run G Plug back to top of sand Drill out cement, clean	amma-Ray Survey to de and cement 5-1/2" line out, and put on product by the survey and put on produ	etermin or at top ion. Send C	ige Corporation Company or Operator Production Superin	· · · · · · · · · · · · · · · · · · ·

noidaulia (a participal participa

.