## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico HOBBS OFFICE OCC

MISCELLANEOUS NOTICES 15 AM 11: 18
Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by Checking	,	<del></del>
Notice of Intention To Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner	x
Notice of Intention to Squeeze	Notice of Intention to Acidize	NOTICE OF INTENTION TO SHOOT (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other)	x
OIL CONSERVATION COMM	ISSION Hobbs. New Mexic	o April 13.	1961
SANTA FE, NEW MEXICO	(Place)	O April 13, (Date)	
Gentlemen:			
Wallandian is a Nasian of Take	anion on the compain work on the state of th		
-	ention to do certain work as described below at the		
	orporation Cap Unit #1		
	oc. 7 , T. 138 , R. 328 ,NM	PM. Caprock Queen	<b>.</b>
T.AA	County,		
	FULL DETAILS OF PROPOSED PLAN (FOLLOW INSTRUCTIONS IN THE RULES AN	-	
1. Propose	to clean out well to TD 3058	feet.	
1. Propose 2. Run and	(FOLLOW INSTRUCTIONS IN THE RULES AN	feet.	
1. Propose 2. Run and 3. Run Gamm	to clean out well to TD 3058 cement approx. 155 feet 328	feet.	
1. Propose 2. Run and 3. Run Gamm	to clean out well to TD 3058 cement approx. 155 feet 32"	feet.	
1. Propose 2. Run and 3. Run Gamm	to clean out well to TD 3058 cement approx. 155 feet 32"	feet.	
1. Propose  2. Run and  3. Run Gamma  4. Sand jet	to clean out well to TD 3058 cement approx. 155 feet 3½ ma Ray log. t perforate liner.	feet.	
1. Propose  2. Run and  3. Run Gamma  4. Sand jet	to clean out well to TD 3058 cement approx. 155 feet 3½ ma Ray log. t perforate liner.	feet.	
1. Propose  2. Run and  3. Run Gazz  4. Sand Je  Approved  Except as follows:	to clean out well to TD 3058 cement approx. 155 feet 3 th  ma Ray log. t perforate liner.	feet. liner through pay.	<b>C</b>
1. Propose  2. Run and  3. Run Gam  4. Sand Je  Approved	to clean out well to TD 3058 cement approx. 155 feet 3 to a Ray log. t perforate liner.  Position	feet. liner through pay.  aridge Corporation Commany or Operation I. Miller gineer	do:

Address.....

Box 334, Caprock, New Mexico