

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name No. 1 No. Caprock Queen Unit
8. Farm or Lease Name No. Caprock Queen Unit
9. Well No. Tract 26, Well No. 8
10. Field and Pool, or Wildcat Caprock Queen (Lea)
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Injection Well
2. Name of Operator Thunderbird Oil Corporation
3. Address of Operator P. O. Box 1778, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>H</u> . <u>1897</u> FEET FROM THE <u>North</u> LINE AND <u>723</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>13-S</u> RANGE <u>32-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7" @ 312' w/150 sx.  
4-1/2" @ 3070' w/250 sx.

1. Displace hole with 2500# per 100 bbls. salt base mud.
2. Set CIBP @ approximately 2950'.
3. Set 35' cement plug (5 sx.) on top of CIBP.
4. Cut off & pull 4-1/2" casing at approximately 1000'.
5. Spot 35 sx. cement plug in-and-out of 4-1/2" casing stub.
6. Spot 35 sx. cement plug in-and-out of 7" casing stub.
7. Spot 10 sx. cement plug at surface and erect 4-1/2" regulation dry hole marker.
8. Clean up location for NMOCC inspection and approval.

100' plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Henry J. Schuman

TITLE President

DATE Feb. 25, 1975

APPROVED BY Joe

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: