

## OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

April 5, 1948 Midland, Texas

Date

Place

OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO  
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the \_\_\_\_\_

H. L. Wilson Drilling Co.

Well No. State #1 in the

Company or Operator

Lease

NE 1/4 of NW 1/4 of Sec. 19, T. 13S, R. 32 E, N. M. P. M.,  
Caprock Field, Lea County.

The dates of this work were as follows: Between March 18 and April 1, 1948

Notice of intention to do the work was (was not) submitted on Form C-102 on March 16, 1948  
and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Split casing from 1267' to 1280' was squeezed by Halliburton Well Cementing Co. with 100 sacks of regular cement on March 15, 1948. Halliburton Cement retainer has now been drilled out, also all cement and plugs to bottom and bailing tests now show the damaged casing to be successfully sealed as no drilling mud, formation, or water has come into the hole. Test was made by bailing fluid to a low level before bottom hole plug was drilled, with an exact marker of fluid top. 12 hour test was made and no fall-up of any kind was shown. Cleaning out shot hole with sand pump is now in progress in preparation for putting well on production: Wilson Drilling Co.

Witnessed by R. E. Throckmorton Company Title Partner

Subscribed and sworn before me this

8th day of April 1948

H. D. Johnson

H. D. JOHNSON, NOTARY PUBLIC  
MIDLAND COUNTY, TEXAS

My commission expires 6-1-49

I hereby swear or affirm that the information given above is true and correct.

Name R. E. Throckmorton

Position Partner

Representing H. L. Wilson Drilling Company

Company or Operator  
Midland, Texas.

Address Box 1517

Remarks:

Name

Title