

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> For <input type="checkbox"/>
5. State Oil & Gas Lease No.
B10083

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Amerada Hess Corporation	State BT "E"
3. Address of Operator	9. Well No.
Drawer D, Monument, New Mexico 88265	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER N      660 FEET FROM THE South      LINE AND 1980 FEET FROM	Hightower Permo-Penn.
THE West      LINE, SECTION 23      TOWNSHIP 12-S      RANGE 33-E      NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4632' DF.	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

September - October 1979

Killed well & pulled 2-3/8" tbg. Ran 3-3/4" drlg. bailer & drld. cement fr. 8789' to 8800' & knocked bridge plug loose at 8800'. Blew bailer up hole & kinked line. Drld. on bridge plug & cement fr. 8844' to 8847'. Ran Klusterite shoe, wash pipe, jars & DC/s on 2-3/8" tbg. & drld. on bridge plug fr. 8848' to 8849'. Pulled tbg. & shoe, re-ran pkr. & tbg. & swabbed hole dry. Ran magnet on sand line & recovered metal cuttings. Re-ran Klusterite shoe, wash pipe, jars & DC's on tbg. & milled on bridge plug at 8848'. Trip out w/tbg. & shoe. Re-ran drlg. bailer & knocked bridge plug loose at 8849' & pushed to 10,104'. Ran pkr. & tbg. & set pkr. at 9895' & swabbed Devonian zone csg. perfs. fr. 9984' to 9996'. Presently flow testing and evaluating.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED EB Lisher TITLE Supv. Adm. Ser. DATE 10-30-79

APPROVED BY Orig. Signed by John Runyan TITLE Geologist DATE NOV -1 1979

CONDITIONS OF APPROVAL, IF ANY (a)