

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Grande Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01063
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-10706
7. Lease Name or Unit Agreement Name State BT "B"
8. Well No. 1
9. Pool name or Wildcat Hightower Permo-Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ TA'd ☐ OTHER ☐	2. Name of Operator Amerada Hess Corporation
3. Address of Operator Drawer D, Monument, New Mexico 88265	4. Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 26 Township 12S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4259' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU & TIH w/5-1/2" gauge ring & junk basket to + 8400' & TOH. TIH w/5-1/2" CIBP & set at + 8400'. Spot 50' cement plug on top of CIBP to 8350'. TIH w/csg. cutters & cut 5-1/2" csg. at + 6650'. TOH & lay down 5-1/2" csg. Run work string & circ. hole w/mud. Pull & spot 100' csg. plug across 5-1/2" csg. stub, 50' above & below cut. Pull & spot 100' cement plug across intermediate shoe fr. 3975' - 3875'. Perforate 8-5/8" csg. at 280'. TIH w/tbg. & pump 50 sks. cement outside perforations & leave 20 sks. cement inside csg. Pull & spot 10 sks. cement at surface. Remove well head, install dry hole marker & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <u>R. L. Wheeler, Jr.</u>	TITLE <u>Supv. Adm. Svc.</u>	DATE <u>8-20-90</u>
TYPE OR PRINT NAME <u>R. L. Wheeler, Jr.</u>		TELEPHONE NO. <u>505 393-2144</u>

(This space for State Use)	APPROVED BY <u>Paul L. Geologist</u>	TITLE <u></u>	DATE <u>AUG 22 1990</u>
----------------------------	--------------------------------------	---------------	-------------------------

CONDITIONS OF APPROVAL, IF ANY:
THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED