

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 13 1970
 Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-10137	
7. Unit Agreement Name	
8. Farm or Lease Name	
State 245	
9. Well No.	
5	
10. Field and Pool, or Wildcat	
Lazy J - Penn.	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- Plugged & Abandoned
2. Name of Operator		
Atlantic Richfield Company		
3. Address of Operator		
P. O. Box 1978, Roswell, New Mexico 88201		
4. Location of Well		
UNIT LETTER	1980	FEET FROM THE North LINE AND 1650 FEET FROM
THE East	LINE, SECTION 28	TOWNSHIP 13-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)		
4244' Grd		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI & RU casing pulling unit 1/31/70. Shot 5½" casing in two @ 4047' at 8-5/8" casing shoe. Pulled 127 jts of 5½" casing. Spotted 30 sk Class A cement plug, half in & half out of 5½" casing stub and across 8-5/8" casing shoe @ 4047'. Shot off 8-5/8" casing @ 600'. Pulled 20 jts 8-5/8" casing (595.69'). Spotted 30 sk Class A cement plug from 560-600' (in and out of 8-5/8" casing stub). Spotted 30 sk Class A cement plug 335-375'. Spotted 10 sk Class A cement plug 0-15'. Set dry hole marker. Well P & A 2/7/70.

We will notify your office by letter when location is cleared and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>O.D. Dretches</u>	TITLE <u>Dist. Drlg. Supervisor</u>	DATE <u>2-11-70</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u>2-11-70</u>
CONDITIONS OF APPROVAL, IF ANY:		