

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Orig²cc: OCC, Hobbs
cc: Regional Office, Santa Fe, N.M.
cc: file

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-10209	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SINCIATR OIL & GAS COMPANY	8. Farm or Lease Name State 251
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240	9. Well No. 3
4. Location of Well UNIT LETTER 0 990 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 13S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Lazy J Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4244' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER Squeeze perfs.& deepen, same form. <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth Drilled 9710'. PBTD 9708. Presently completed in Penn perfs. 9596-9708' and producing 8 BOFD and 0 BWPD.

PROPOSE TO: Squeeze cement perforations 9596-9708', drill cement and test squeeze and casing. Drill out shoe and deepen to approx. 9765'. Acidize Penn open hole 9708-9765' w/approx. 2,000 gals. acid. Test and put on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie N. Clement TITLE Superintendent DATE August 15, 1968
APPROVED BY Leslie N. Clement TITLE Oil & Gas Inspector DATE AUG 16 1968
CONDITIONS OF APPROVAL, IF ANY: