State of New Mexico Form C-103 Submit 3 Conies to Appropriate Energy, Minerals and Natural Resources Revised March 25, 1999 District Office WELL API NO. DISTRICT I 1625 n. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION 30-025-0109600 DISTRICT II Indicate Type of Lease 811 South First, Artesia, NM 88210 2040 South Pacheco STATE |X|FEE DISTRICT III Santa Fe, NM 87505 State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV K-3657 2040 S. Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) State of NM T Type of Well Other Oil Well X Gas Well 8. Well No. Name of Operator 1 Dominion Oklahoma Texas Expl. & Prod. Inc. Pool name or Wildcat Address of Operator 14000 Quail Springs Parkway - Suite 600 - Oklahoma City, OK 73134 Baum Upper Penn Well Location 1980' feet from the East line. South line and 660' feet from the 0 Unit letter **NMPM** County **13S** Range 33E Township 10. Elevation (Show whether DR, RKB, RT, Gr, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING X REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK COMMENCE DRILLING OPNS. PLUG AND CHANGE PLANS TEMPORARILY ABANDON **ABANDONMENT** CASING TEST AND CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propropsed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Spot 100' cmt plug above top perf @ 9,458'. 2. Spot 100' cmt plug @ kick off point, 7,414'. 3. Cut off 4 1/2" casing and spot 100' cmt plug, 50' in and 50' out. Tag top of cmt. 4. Spot 100' cmt plug @ shoe of 9 5/8" csg, from 4113' to 4013'. Tag top of cmt. 5. Spot 100' cmt plug @ top of Rustler formation, from 1700' to 1600'. FD 6. Spot 100' cmt plug, 50' in and 50' out of the 13 5/8" casing, @ 357' to 257'. 7. 20 sx cmt plug @ surface. 8. Weld on cap with information, clean location.

See attached Schematic

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE **SIGNATURE**

Regulatory Specialist

405-749-5263 Carla Christian Telephone No. Type or print name

(This space for State use)

JAN 22 2003

DATE

01/14/03

TITLE APPROVED BY Conditions of approval, if any:

ORICHIA! SIGNED BY

THE COMMISSION MUST BE NOTIFIED 24 OC FIELD REPRESENTATIVE II/STAFF MANAGER TO THE BEGINNING OF PLUCGING CIPEDATIONS FOR THE C-103

TO BE APPROVED.

State of N.M. "T" #1 API # 30-025-01096 Prop. No. 263880.001 Sec.32 T13S R33E Lea County, New Mexico GL 4267' Spud Date: 1/15/69 Comp. Date: 3/7/69 KB 4279' 20 sx cmt plug @ surface 'lug 50' in and out of 13 3/8' 48# set @ 307' cmt w/300 sx. 3 3/8" casing 00' cmt plug from 1600 to 700'. Rustler form @ 1700' 9 5/8" 11.6# N-80 & J-55 @ 4063 ' 'lug 50' in and out of 9 5/8" Cmt w/2250 sx Plug 50' in and out of cut off, tagged. Est @ 5000'. Notes: Casing collar @ 7,394' Squeezed casing hole @ 7,400' w/ 100 sx 10/88 -100' cmt plug @ kick off point. Cement Plug @ 7,414'-7,550' 4 1/2" 11.6# N-80 & J-55 Kick off point. @ 9,940' w/ 250 sx FOC @ 9200' -15 sx cmt @ 9400' enn perfs -5 ½" 15.5 & 17# J-55 @ 9,870' !458 to 9630 Top casing cut @ 8,015' OA) Cement Top Unknown enn perfs 1,769' - 9,883'

CIBP @ 9,600'

TD

PBTD 9,930 TD 9,948' Dominio. Exploration & Production