Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088

WELL API NO.

P.O. BOX 1960, 110008, 1411 00240	1.0. Don 2000		30-025-01097			
Santa Fe, New Mexico 87504-2088 Sonta Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE XX FEE			
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. V-3834			
	AND DEPORTS ON WEL	1.6			7	
SUNDRY NOTICE: (DO NOT USE THIS FORM FOR PROPO- DIFFERENT RESERVOI (FORM C-101)	7. Lease Name or Unit	Agreement Name				
1. Type of Well: OIL GAS WELL X WELL	Sapphire ALE State					
2. Name of Operator YATES PETROLEUM CORPORATI	8. Well No.					
3. Address of Operator			9. Pool name or Wildcat			
105 South 4th St., Artes	ia, NM 88210		Lazy J Penn	Lazy J Penn		
4. Well Location Unit Letter I: 1980	Feet From The South	Line and 660	Feet From The	East Li	ne	
Section 33	Township 13S Ra		NMPM I	Lea County	77	
	10. Elevation (Show whether 4248	DF, RKB, RT, GR, etc.) GR				
Check An	propriate Box to Indicate	Nature of Notice. R	eport, or Other D	ata		
NOTICE OF INTE	PORT OF:					
	PLUG AND ABANDON	REMEDIAL WORK	_	LET RENEW	\square	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN		UG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND C				
OTHER: Deepen well pani			Post.	X		
OTHER:						
12 Describe Proposed or Completed Operation work) SEE RULE 1103. 7-10-92. RUPU. ROH w/rod 100 bb1s 39 vis 24#/bb1 LG Test RBP to 1000 psi. Test w/globe basket, drill collad Wash and ream from 9705-9. TD hole 10:15 AM 7-16-92. joints liner with Atlas B get into 5½" casing stub hanger and 2-7/8" tubing of liner set 9429'. Hang flush 102, 75 sx Class "H Displaced 61.8 bb1s. Bum setting tool and 2-7/8" t	ds and lay down 2-3/8 CM. Got circulation sted annulus to 1000 lars and 2-7/8" tubin and globe basker. 815'. Started drill TOH w/tubing, dril radfor FL 45 threads at 3176'. Modify litto 10100'. Bottom 1 er did not set. RU w/4/10% CFR-3, 2/1	B" tubing. TIH work TIH work RBP, posi, OK. TOH wong to 9676'. RU TIH work shoe, driing 7:30 PM 7-11 collars and be asker liner hor shoe. TIH iner at 10100'. and circulated 0% Halad 22A, 3 Had full cir	w/2-7/8" N-80 acker and 2-7/ /2-7/8" tubing power swivel. 11 collar, 2-7 4-92. Drilled it. TIH w/16 j anger and 2-7/ w/liner, Baker Landing coll 2 hrs. Cement #/sx KCL (yiel culation durin	tubing to 9700'. 8" tubing to 948, packer and RBP Globe basket p /8" tubing to 96 from 10060-1010 ts 4" 11# J-55 f 8" tubing. Could liner, Baker 1i ar set 10057'. ed liner w/500g. d 1.18, wt 15.6) g cement job. TO	TIH lugged. 74'. 0'. lush not ner Top Super	
I hereby certify that the information above is true an	d complete to the best of my knowledge an	d belief. (con	tinued on page	2)		
- 1 1		TE Production S	Supervisor	_ DATE8-15-92		
	Goodlett			ТЕLEPHONE NO. 505/748	<u>8-1</u> 471	
(This space for State Use) ORIGINAL SIGNED				AUG 17	'92	
APPROVED BY DISTRICT 1.5	<u> </u>	TLE -		- DATE -		

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

Revised	1-1-89

WELL API NO.

1.0.201.1.001,1.001	P.O. Box 2088		30-025-01097		
Santa Fe, New Mexico 87504-2088 O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS			6. State Oil & Gas Lease V-3834		
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. (FORM C-101) FO	7. Lease Name or Unit A	greement Name			
1. Type of Well:					
OIL GAS WELL OTHER DEEPEN WELL			Sapphire ALE	State	
2. Name of Operator YATES PETROLEUM CORPORATION			8. Well No. 1		
3. Address of Operator			9. Pool name or Wildcat		
105 South 4th St., Artesia,	, NM 88210		Lazy J Penn		
4. Well Location Unit Letter I : 1980 Fee	et From The South	Line and660	Feet From The _	East Line	
11. Check Appro	waship 13S Ra 10. Elevation (Show whether 4248' GR opriate Box to Indicate I	DF, RKB, RT, GR, etc.) Nature of Notice, Re			
NOTICE OF INTENT	SEQUENT REPO	ORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTE	RING CASING	
TEMPORARILY ABANDON C	CHANGE PLANS	COMMENCE DRILLING	OPNS. L PLUG	AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB					
OTHER:		OTHER: Perfora	te, Treat	X	
12. Describe Proposed or Completed Operations (Cowork) SEE RULE 1103. (page 2 - continued) RU and 1000 psi for 15 mins, OK. scraper, 2-3/8" tubing and 10027-10057'. Tested 4" 15 TOH w/2-7/8" tubing, 2-3/8' to 4825'. Perforated 9656-12, 22, 54, 9947, 53, 88, 915% NEFE acid. Re-perforate 27, 41, 42, 47, 48, 63, 64, 55, 56, 9947, 48, 50, 51, 51 total 55 holes. Acidized to recover load. 7-26-92. Unset packer at 92-3/8" tubing. Turn over 10.	d drill cement from TOH w/2-7/8" tubing to 1 iner to 1000 psi for tubing, scraper at 10007' w/16 .33" ho 10007 w/16 .33" ho 10002 and 10007 ted as follows: 96, 67, 68, 73, 74, 752, 53, 59, 62, 88, perforations 9654-19608' TOH w/100 jt	n 8515-9424' top ng, drill collar 10027'. RU powe or 15 mins, OK. and bit. TIH w/ oles as follows: 7'. Acidized per 554, 55, 57, 64, 79, 84, 95, 99, 89, 93, 94, 98 10035' w/13000 g	of liner. Tests and bit. TIHER swivel and dr Circulated cast 2-3/8" tubing a 9656, 66, 974 rforations 9656-65, 67, 9718, 9800, 01, 12, 13, 10001, 14, 33 tals 15% NEFE ac	ted liner top to w/3-1/8" bit, illed cement from ing w/2% KCL water. nd 2-7/8" tubing 1, 47, 68, 73, 9800 10007' w/6000 gals 20, 21, 24, 25, 26, 3, 14, 22, 23, 54, 34 and 10035', id. Swabbed well	
I hereby certify that the information above is true and com					
, , ,	- rellett m		upervisor	8-15-92	
TYPE OR PRINT NAME Juanita Goo		· · · · · · · · · · · · · · · · · · ·		а <u>лерноне но. 505/748—1</u> 471	
(This space for State Use)				#HO 1 7 100	
Calor de la company			_	AUG 17'92	
APPROVED BY		TE	D/	ATE	