

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator H. S. Moss		8. Farm or Lease Name State C
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240		9. Well No. 2
4. Location of Well UNIT LETTER C 330 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 34, TOWNSHIP 13 RANGE 33 NMPM.		10. Field and Pool, or Wildcat Lazy "J"
15. Elevation (Show whether DF, RT, CR, etc.) 4241' D.F.		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 sx cement plug at 9600'.
2. Spotted a 35 sx cement plug at 5-1/2 casing stub at 5450'.
3. Spotted a 25 sx cement plug at 8-5/8 casing shoe at 4034'.
4. Spotted a 25 sx cement plug at 8-5/8 casing stub at 620'.
5. Spotted a 25 sx cement plug at 13-3/8 casing shoe at 317'.
6. Spotted a 10 sx cement plug at surface with marker.
7. Hole was loaded with mud-laden fluids.
8. Well was plugged and abandoned on 6/22/71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. S. Moss TITLE Agent DATE 6/24/71

APPROVED BY H. S. Moss TITLE OIL & GAS INSPECTOR DATE JUL 30 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 25 1971

OIL CONSERVATION COMM.
HOBBES, N. H.