

(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-01124	
2. NAME OF OPERATOR Texaco Producing Inc.		8. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR PO Box 728, Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter F, 1650' FNL & 1650' FWL		8. FARM OR LEASE NAME Willard Beaty	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4222' DF		10. FIELD AND POOL, OR WILDCAT Lazy J Penn	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, T-13-S, R-33-	
		12. COUNTY OR PARISH Lea	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) MIRU pulling unit, 4/15/88. Pull rods. Install BOP. Pull tubing.
- 2) RIH with 5 1/2" packer on tubing. Set packer at 9484'.
- 3) Acidize perfs at 9643'-9783' (129 holes) with 3000 gallons of 15% NEFE containing 2 drums of mutual solvent and 2 drums of scale inhibitor, 130 ball sealers, and 500# rock salt in gelled brine.
- 5) Release packer. POH.
- 6) Run production equipment. Place well on production. Rig down pulling unit.

18. I hereby certify that the foregoing is true and correct

397-3571

SIGNED

TITLE Hobbs Area Superintendent

DATE 6/3/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JUN 3 10 33 AM '88

*See Instructions on Reverse Side

RECEIVED
JUN 3 1988
CARLEBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.