

30-022-01118

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JUL 11 11 41 AM '69

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3431
7. Unit Agreement Name -
8. Farm or Lease Name State "7"
9. Well No. 1
10. Field and Pool, or Wildcat Baum (Up. Penn)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	
2. Name of Operator Coastal States Gas Producing Company	
3. Address of Operator P. O. Box 235, Midland, Texas 79701	
4. Location of Well UNIT LETTER C, 330 FEET FROM THE North LINE AND 1568.8 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 14S RANGE 33E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4273' GR	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well No. 1 was plugged and abandoned 7-14-69 with 3999' of 5-1/2" csg. recovered. Plugs were set as follows:

1. Set cast iron bridge plug @ 9540' w/20' cmt. on top.
2. Set 50 sx @ 3999-3899' (top of 5-1/2").
3. S t 10 sx @ 20' to surface.
4. Cement circulated around 8-5/8" set @ 4060' - 8-5/8" was not pulled.
5. Installed permanent dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe R. Howard</u>	TITLE <u>Division Production Manager</u>	DATE <u>July 30, 1969</u>
APPROVED BY <u>John W. Runyon</u>	TITLE <u>Geologist</u>	DATE <u>SEP 24 1969</u>
CONDITIONS OF APPROVAL, IF ANY:		