

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-01145 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name State "J" |
| 8. Well No. #2 |
| 9. Pool name or Wildcat Saunders Permo Upper Penn |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | |
| 2. Name of Operator Charles B. Gillespie, Jr. | |
| 3. Address of Operator P.O. Box 8 Midland, Texas 79702 | |
| 4. Well Location Unit Letter L : 198 Feet From The South Line and 660 Feet From The West Line Section 23 Township 14-S Range 33-E NMPM Lea County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4204 DF | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set Cibp @ 9500'. Cap with cement.
2. Spot 100' plug @ 6500'.
3. Spot 100' plug @ 7 5/8" shoe @ 4167'.
4. Spot 100' plug @ 5 1/2" liner top @ 4050'. *NOTE: TOP OF CEMENT ON 7 5/8" 1800'*
5. Spot 100' plug @ 10 3/4" surface casing shoe @ 294'.
6. Put 15 sx surface plug. *WILL NEED TO PERFORM 3 IS*
7. Weld on 4" dry hole marker. *PLACE MIN 50 SX OUTSIDE WITH 100' INSIDE*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Kevin Widner* TITLE Production Manager DATE 10/11/93
TYPE OR PRINT NAME Kevin Widner TELEPHONE NO (915) 883-1765

(This space for State Use)

APPROVED BY *Jerry Sexton* TITLE ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR OCT 14 1993

CONDITIONS OF APPROVAL, IF ANY:

THE COMPLETION MUST BE NOTIFIED
AND THE STATE MUST BE NOTIFIED OF
PLUGGING OPERATIONS FOR THE CLOSURE
OF THE WELL.