

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-2075

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
6. Indicate Type of Well OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
Name of Operator Charles B. Gillespie, Jr.	8. Farm or Lease Name State J
Address of Operator P.O. Box 8 Midland, Texas 79702	9. Well No. 3
Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM West LINE, SECTION 23 TOWNSHIP 14S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Saunders Permo-Penn
11. Elevation (Show whether DF, RT, GR, etc.) 4198 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 25 sx plug across perforations 9754-58', 9769-80', 9790-9801', 9856-61'.
1-25 SX PLUG AT 7700'
- Set 25 sx plug across liner top at 4080'. 5 1/2" casing will be filled with mud between plugs.
- 8 5/8" casing will be pulled from approximately 1500'.
- Set 50 sx plug across 8 5/8" casing stub.
- Set 25 sx plug across base of 13 3/8" surface casing at 296'. Hole will be filled with mud between plug across 8 5/8" casing stub and plug at base of 13 3/8" surface casing.
- 10 sx plug will be set at top of surface casing.
- 4" marker will be welded to surface pipe and location cleaned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>David Hartig</i>	TITLE <u>Engineer</u>	DATE <u>5/15/85</u>
APPROVED BY <u>DISTRICT SUPERVISOR</u>	TITLE _____	DATE <u>JUN 10 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 16 1985

NOV 16 1985