

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

1a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Charles B. Gillespie, Jr.

Address of Operator

P.O. Box 8 Midland, Texas 79702

Location of Well

UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM

THE East LINE, SECTION 33 TOWNSHIP 14S RANGE 33E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

Stevens

9. Well No.

7

10. Field and Pool, or Wildcat

Saunders Permo-Penn

15. Elevation (Show whether DF, RT, GR, etc.)

4216 DF

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

REWORK OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPERATIONS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 25 sx plug across perforations 9822-9845', 9854-9860', 9878-9888', 9898-9906', 9956-9980'.
- 25 SX plug @ 770'
2. Set 25 sx plug across liner top at 4017'. 5 1/2 casing will be filled with mud between plugs.
3. 8 5/8" casing will be pulled from approximately 1400'.
4. Set 50 sx plug across 8 5/8" casing stub.
5. Set 25 sx plug across base of 13 3/8" surface casing at 318'. Hole will be filled with mud between plug across 8 5/8" casing stub and plug at base of 13 3/8" surface casing.
6. 10 sx plug will be set at top of surface casing.
7. 4" marker will be welded to surface pipe and location cleaned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Daniel Harty

TITLE

Engineer

DATE

5/15/85

ORIGINAL SIGNED BY JERRY BAXTON

DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE

JUN - 7 1985

CONDITIONS OF APPROVAL, IF ANY: