

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  Stevens
8. Well No. 8
9. Pool name or Wildcat Saunders Permo Upper Penn

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Charles B. Gillespie, Jr.	
3. Address of Operator P. O. Box 8 Midland, Texas 79702	
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4215' DF	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/14/88: Set cast iron bridge plug at 9750'. Dumped 4 sx cement on top of bridge plug.  
12/15/88: Tagged cement at 9715'. Circulated hole with salt gel mud. Set 25 sx plug at 7694'. Set 25 sx plug at 4062'.  
12/16/88: Tagged cement plug at 4004'. Ran casing cutter. Attempted to pull 8 5/8" casing from 1858', failed to move. Ran tubing to 1901'. Broke circulation and pumped 50 sx at 1901'.  
12/19/88: Tagged cement plug at 1744'. Set 25 sx plug at 1592'. Perforated 8 5/8" casing at 308'. Circulated cement behind 8 5/8" casing to surface with 135 sx. Tagged cement plug at 191'. Set 10 sx plug at top of surface casing. Welded 4" marker to surface casing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David W. Hastings TITLE Production Manager DATE 3/17/89  
TYPE OR PRINT NAME David W. Hastings TELEPHONE NO. (915) 683-1765

(This space for State Use)

APPROVED BY David R. Smith TITLE OIL & GAS INSPECTOR DATE 3/17/89  
CONDITIONS OF APPROVAL, IF ANY:

R N

E