NO. OF COPIES RECEIVED				C-103	
DISTRIBUTION				sedes Old and C-103	
ANTAFE	NEW MEXICO OIL CONSERVA	TION COMMISSION		ive 1-1-65	
ILE	<del></del>				
.S.G.S. AND OFFICE	_		i	te Type of Lease	
PERATOR			State		ee
FERMION	J		S. State O	dl & Gas Lease No	·.
SUNI (DO NOT USE THIS FORM FOR USE "APPLIE	DRY NOTICES AND REPORTS ON WELL PROPOSALS TO ORILL OR TO DEEPEN OF PLUG BACK TO CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPE	S A DIFFERENT RESERVOIR.			
OIL CAS WELL WELL	OTHER-	5ALS.)	7. Unit Ag	greement Name	111111
Name of Operator			8. Form or	Lease Name	
Petroleum Corpora	tion of Texas		State	9 "SC"	
Address of Operator			9. Well No	).	
c/O Hobbs Pipe &	Supply P.O. Box 2010 Ho	bbs, N M	1		
				and Pool, or Wilde	
UNIT LETTER	GGO FEET FROM THE NOTTH LINE	AND 1986 FEET	FROM Sauno	lers (Perr	:o-Per
	TION 33 TOWNSHIP 143		NMPM.		
	15. Elevation (Show whether DF, RT	CP		111111111	77777
		, on, eic.)	12. County		
	4221' D.F.		<u> Lea</u>		711111
Check	Appropriate Box To Indicate Nature				
NOTICE OF	INTENTION TO:	SUBSEQ	UENT REPORT	ΓOF:	
REFORM REMEDIAL WORK		<b>-</b> -	7		
AT DAM REMEDIAL WORK		SIAL WORK	1	ALTERING CASING	ii
		<u> </u>	╡		==
<b> </b>	СОММІ	ENCE DRILLING OPNS.		PLUG AND ABANDON	MENT X
<del>  </del>	CHANGE PLANS CASING	ENCE DRILLING OPNS.			MENT X
ULL OR ALTER CASING	CHANGE PLANS CASING	ENCE DRILLING OPNS.	] ] 		MENT X
OTHER	CHANGE PLANS CASING	ENCE DRILLING OPNS.  G TEST AND CEMENT JQB  HER	]	PLUG AND ABANDON	[]
OTHER	CHANGE PLANS CASING	ENCE DRILLING OPNS.  G TEST AND CEMENT JQB  HER	luding estimated do	PLUG AND ABANDON	[]
OTHER	CHANGE PLANS CASING	ENCE DRILLING OPNS.  G TEST AND CEMENT JQB  HER	luding estimated de	PLUG AND ABANDON	[]
OTHER  Describe Proposed or Completed work) SEE RULE 1103.  1. Spotted a 35 s 2. Spotted a 25 s	Operations (Clearly state all pertinent details, and x. cement plug across per x. cement plug at $5\frac{1}{2}$ " cas	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5	9854'-987 5300'.	PLUG AND ABANDONS	
OTHER  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  A. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8"	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
OTHER  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1103.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  A. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8"	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
OTHER  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
OTHER  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1103.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	[]
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	[]
other  Describe Proposed or Completed work) SEE RULE 1103.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1103.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Other  Describe Proposed of Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s 5. Hole was loade	Change Plans  Ch	forations at ing stub at a casing shoe a with marker.	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s 5. Hole was loade	CHANGE PLANS  CHANGE PLANS  CASING OTT  CASING OTT  OPERATIONS (Clearly state all pertinent details, and ott)  X. cement plug across per X. cement plug at $5\frac{1}{2}$ " cas X. cement plug at 8 5/8" X. cement plug at surface	forations at ing stub at a casing shoe a with marker.	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	
other  Describe Proposed or Completed work) SEE RULE 1703.  1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 10 s 4. Spotted a 10 s 5. Hole was loade	Operations (Clearly state all pertinent details, and x. cement plug across per x. cement plug at $5\frac{1}{2}$ " cas x. cement plug at 8 5/8" x. cement plug at surface d with mud laden fluids.	ence DRILLING OPNS.  G TEST AND CEMENT JQB  HER  d give pertinent dates, inc  forations at ing stub at 5 casing shoe a with marker.	9854'-987 5300'. at 4141'/	ate of starting any	
1. Spotted a 35 s 2. Spotted a 25 s 3. Spotted a 25 s 4. Spotted a 10 s 5. Hole was loade	Operations (Clearly state all pertinent details, and x. cement plug across per x. cement plug at $5\frac{1}{2}$ " cas x. cement plug at 8 5/8" x. cement plug at surface d with mud laden fluids.	forations at ing stub at a casing shoe a with marker.	9854'-987 5300'. it 4141'/	PLUG AND ABANDONS	

## RECEIVED

. .ð

3

.

ART 1570

OH. C. THE CO. THE CHIMM.