

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

7. Unit Agreement Name	

8. Farm or Lease Name	
M. H. Saunders	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Saunders Permo Penn	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	Plugged and Abandoned
2. Name of Operator	
Skelly Oil Company	
3. Address of Operator	
P. O. Box 1351, Midland, Texas 79701	
4. Location of Well	
UNIT LETTER <u>C</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4199' GR	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF;

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in and rigged up pulling unit 1-8-72. Cut stuck tubing at 9501' and pulled.
- Spotted 50-sack cement plug 9296-9506'.
- Loaded hole with 10# mud.
- Found casing free at 5100', shot off casing at 5125' and pulled.
- Spotted cement plugs as follows:

10# mud 9296-6150'
50 sacks cement 6150-5690'
10# mud 5690-5150'
50 sacks cement 5150-4950'
10# mud 4950-4325'
50 sacks cement 4325-4150'
10# mud 4150-30'
10 sacks cement 30' - Surface

6) Set marker.

Well plugged and abandoned January 13, 1972.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief,

SIGNED (Signed) D. R. Crow TITLE Lead Clerk DATE Jan. 19, 1972

APPROVED BY Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE MAR 6 1972

CONDITIONS OF APPROVAL, IF ANY:

100-100000

100-100000

100-100000

RECEIVED

JAN 2 1962

OIL CONSERVATION COM.
WASHINGTON, D. C.

100