2. Tomor Character Weldon S. Grest & I. J. Wolfson Weldon S. Grest & I. J. Wolfson M. H. Saunders (A. Cardien of Weldon S. Grest & I. J. Wolfson M. H. Saunders (A. Cardien of Weldon S. Grest & I. J. Wolfson M. H. Saunders (A. Cardien of Well (A. Cardie			
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION Creation of Conservation Commission Creation of Conservation Creation C	NO. OF COPIES RECEIVED		
NEW MEXICO OIL CONSERVATION COMMISSION Check To be a conserved to the conservation of	DISTRIBUTION		
Section of the property of t	SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	
State Stat			
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS TO SHAPE AND		_	
SUNDRY NOTICES AND REPORTS ON WELLS 1. Street		_	
The state of Country Section 1 to 1	OPERATOR		o, state on a das Lease No.
2. Votes of Clearing Weldon S. Guest & I. J. Wolfson M. H. Saunders Weldon S. Guest & I. J. Wolfson M. H. Saunders V. Well Reports & Gas Services, Inc., Box 763, Hobbs, N.M. 88240 4. Cocation of Welt West Wes		RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
Weldon S. Quest & I. J. Wolfson 3. Address of Species CO OLI Reports & Gas Services, Inc., Box 763, Hobbs, N.M. 88240 4. Cocution of Well Will Large D 660 **CET FROM THE LINE ASS 10. Flaid and Pool, or Wildon Sunders Person Penn The Wost Line, SECTION 34 **Construct Person Penn 15. Elevation (More wheled DF, RT, GR, etc.) 4212 KB Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: **ELUS AND ABAADON** PLUS AND ABAADON**	OIL GAS WELL WELL	OTHER-	
2. Addition of Operator c/o Cill Reports & Cas Services, Inc., Box 763, Hobbs, NM. 88240 3. A Condition of Wolf 2. A Condition of Wolf 3. A Condition of Wolf of	·	T. J. Walfson	1 '
c, cection of Well 4, cection of Well 4, cection of Well 5, cection of Well 6, cection of Well 6, cection of Well 6, cection of Well 7, cection of Well 15, Elevation (Show whether Dr. NT, CR, etc.) 60 60 60 60 60 60 60 60 60 6		To do MOTIPOSI	
Saunders Permo Penn The West Line, Section 34 Township 14 S And 2 33 E NAME 15, Elevation (Show whenher DF, RT, GR, etc.) 12, County	c/o Oil Reports & Gas	s Services, Inc., Box 763, Hobbs, N.M. 88240	3
The West Line, SECTION 34 TOWNSTIF 14 S NAME 33 E NAME 12, County		660 FEET FROM THE North LINE AND 660 FEET FRO	Saunders Permo Pann
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: BENFORM REMEDIAL WORK TEMPORAPILY ABANDON TEMPORAPILY ABANDON THANGE PLANS THANGE PLANS THANGE PLANS THANGE PLANS THE RULE INDICATED AND ABANDONMENT THE RULE INDICATED AND ABANDONMENT TOTHER Subject well plugged 3/21/74 as follows: Set CIBP @ 9697 & capped with 35' coment Out & pulled 5 1/2" caeding from 71.68' Spot 35 Sack plug @ 71.68' Spot 35 Sack plug @ 5550 Spot 60 sack plug 4250 to 4350 10 sacks at surface with regulation marker Mid between all plugs. Location is ready for inspection.			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PELIC AND ABANDON PLUC AND ABANDON PLUC AND ABANDON CHANGE PLANS CHANGE P			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PEGG AND ABANDON PLUG AND ABANDON CHANGE PLANS CHANGE			
17. Describe Proposed or Completed Operations (Clearly state all pertinent data), and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Subject well plugged 3/21/74 as follows: Set CIBP @ 9697 & capped with 35' coment Out & pulled 5 1/2" casing from 7168 Spot 35 Sack plug @ 7168 Spot 35 Sack plug @ 5550 Spot 60 sack plug & 4250 to 4350 10 sacks at surface with regulation marker Mud between all plugs. Location is ready for inspection.	PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT
Subject well plugged 3/21/74 as follows: Set CIBP @ 9697 & capped with 35' cement Out & pulled 5 1/2" casing from 7168 Spot 35 Sack plug @ 7168 Spot 35 sack plug @ 5550 Spot 60 sack plug @ 5550 10 sacks at surface with regulation marker Mud between all plugs. Location is ready for inspection.	OTHER		
10 sacks at surface with regulation marker Mud between all plugs. Location is ready for inspection. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		Set CIBP @ 9697 & capped with 35° cement Out & pulled 5 1/2" casing from 7168 Spot 35 Sack plug @ 7168 Spot 35 sack plug @ 5550	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		10 sacks at surface with regulation marker	•
1/		location is ready for inspection.	
	•		DATE 5/17/74

Jaly Jak

CONDITIONS OF APPROVAL, IF ANY: