NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSE	Effective 1-1-65	
FILE			
U.S.G.S.			State Fee Fee
LAND OFFICE	_		
OPERATOR			5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
OIL GAS WELL WELL	OTHER•		7. Unit Agreement Name
2. Name of Operator  Culf Oil Corporation			8. Farm or Lease Name Maud Saunders
3. Address of Operator			9. Well No.
Box 670, Hobbs, New Mexico 88240			3
4. Location of Well  UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM			10. Field and Pool, or Wildcat Saunders Fermo Penn
THE WORK LINE, SECTION 34 TOWNSHIP 14-S RANGE 33-E NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)			
	15. Elevation (Show whether I	1192 ' GL	12. County
			***********
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB	
OTHER Plug and Abar	ndon	OTHER	
17. Describe Proposed or Complete work) SEE RULE 1503.	d Operations (Clearly state all pertinent deta	ils, and give pertinent dates, including	estimated date of starting any proposed
9925' TD, 9919' PB.			
Set CI BP at approximately 98001. Circulate hole with heavy mud. Run free point and cut			
and recover 7" casing. Spot 100', 30 sack, cement plug No. 1 in and out of 7" casing stub.  Spot 100', 10 sack, cement plug No. 2 across 9-5/8" casing shoe at 1219'. Cut and recover			
9-5/8" casing from approximately 1500'. (If unable to recover at least 750' of 9-5/8", will			
not only casing). It	able to recover 9-5/8" ca	sing will spot 100', 55	sack, coment plug No.
not pull casing). If able to recover 9-5/8" casing will spot 100', 55 sack, cement plug No. 3 in and out of 9-5/8" stub. Spot 100', 75 sack, cement plug No. 4 across 13-3/8" shoe at			
297'. Spot 40 sack cement plug No. 5 from 50' to surface. Install dry hole marker and clean			
location.			
<u> </u>	Commence of the Commence of th		
$\lambda$			
	/		
18. I hereby certify that the informa	ation above is true and complete to the best o	f my knowledge and belief.	
ORIGINAL SI	GNED BY	a Dandardian Managar	January 10 1071
SIGNED C. D. BOR	LAND TITLE ATE	a Production Manager	January 19, 1971
Jan A		200 21 Clied 6	DATE JAN 31 1971
APPROVED BY	ACAMED TITLE	STACE STACE	DATE AND A LOUIS
CONDITIONS OF APPROVAL, IF	ANY:		

<u>j</u>\*:

## RECEIVED

JAN 2 1971 OIL CONSERVATION COMM. NOODS, N. IJ.