

Ran 401' 13 3/8" casing. Mixed 396 sx. cement and pumped in casing. When bottom plug hit shoe and plugged, cement failed to pump out. Pressure went to 1200# and casing parted at top collar in cellar and dropped. Attempted to clean out cement inside casing and found bad casing condition second joint from top and at 338'. Unable to pull casing. 82' cement in bottom of casing 319' to 401'. Placed cement plug in top of casing from surface to 50'. P & A 5-19-58.

Gulf Oil Corporation
Maud Saunders # 4X

Location: 1830' FSL & 660' FWL Sec. 34-T14S-R34E