

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERFORATE OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR REPERFORATE FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Gulf Oil Corporation	
3. Address of Operator Box 670, Hobbs, New Mexico 88240	
4. Location of Well UNIT LETTER <u>L</u> <u>1815</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>14-S</u> RANGE <u>33-E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.) 4199' GL	

7. Unit Agreement Name
8. Farm or Lease Name Maud Saunders
9. Well No. 4
10. Field and Pool, or Wildcat Saunders Permo Penn
12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPHS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
Plugged and abandoned.			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9980' PB.
Pulled producing equipment. Set CI BP at 9700'. Loaded hole with abandonment mud. Tested casing with 800#, 30 minutes, OK. Capped BP with 20 sacks, 150' of cement, abandoning perforations 9790' to 9960'. Cut and recovered 5-1/2" casing from 4597'. Spotted 100' cement plug from 4647' to 4547', across 5-1/2" casing stub. Spotted 100', 50 sack Class C cement from 4330' to 4230', across 8-5/8" shoe at 4280'. Spotted 100', 40 sack Class C cement from 1650' to 1550' across top of salt. Spotted 50', 18 sack cement plug from 50' to surface. Installed dry hole marker and cleaned location. Completed P & A March 8, 1977.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>D. F. Berlin</u>	TITLE <u>Area Engineer</u>	DATE <u>March 8, 1977</u>
APPROVED BY <u>Eddie Lea</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAR 23 1979</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAR 1 1977

OIL OIL OIL OIL OIL
OIL OIL OIL OIL OIL