

OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

Miscellaneous Reports on Wells

RECEIVED

OCT - 5 1950

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<input checked="" type="checkbox"/>		

October 2, 1950

Mammoth, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

Amerada Petroleum Corporation State of **N.M.** Well No. **1** in the
Company or Operator Lease
C/M/4 NE/4 of Sec. **35**, T. **14-S**, R. **33-E**, N. M. P. M.,
Wildcat Field **Lee** County.

The dates of this work were as follows: **September 30th & October 1st, 1950**

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on **September 29,** 19 **50**
and approval of the proposed plan was ~~obtained~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

10040' - Total Depth - Line. Spotted 35 sacks cement from 10005' to 9682'. Jetted off 5-1/2" casing at 6576' & recovered 6602.43'. Plug from 5700' to 5586' with 35 sacks cement, plug from 4600' to 4486' with 35 sacks cement. Jetted 8-5/8" casing at 480' & recovered 468.73'. Spotted cement plug, using 70 sacks cement, at 350'. Plugged top of 13-3/8" surface casing with 10 sacks cement. Set a piece of 4" Line Pipe, as marker, in top of surface casing, extending four (4') feet above ground level. Well plugged & abandoned at 10:45 A.M., October 1, 1950.

Witnessed by **E. E. Shirley** **Amerada Petroleum Corporation** **Farm Boss**
Name Company Title

Subscribed and sworn before me this

3rd day of **October**, 19**50**

Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name **Dr. [Signature]**

Position **Assistant District Superintendent**

Representing **Amerada Petroleum Corporation**
Company or Operator

My commission expires **10-24-53**

Address **Drawer D, Mammoth, New Mexico**

Remarks:

APPROVED

Date **OCT - 5 1950**

Ray [Signature]
Oil & Gas Inspector

Title