

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1233	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- DRY HOLE		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name STATE A2
3. Address of Operator BOX 68, HOBBS, N. M. 88240		9. Well No. 1
4. Location of Well UNIT LETTER A 660' FEET FROM THE NORTH LINE AND 660' FEET FROM THE EAST LINE, SECTION 34 TOWNSHIP 12-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat WILDCAT
15. Elevation (Show whether DF, RT, GR, etc.) 4164' RDB		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Physical abandonment of hole concluded 4-26-73.
Plugged and abandoned as follows:
- Spotted 30 cu cement plug from 5490 - 5100 (Pays 5440-55)
- Shot 4 1/2" Pcg @ 4255 & 3301' and pulled from 3301'.
- Spotted 50 cu cement plug in + out of stub back to 3150'.
- Shot & pulled 8 7/8" Pcg from 812'.
- Spotted 50 cu plug in & out of 8 7/8" stub.
- " 75 cu " @ 400' (13 7/8" CSA 407')
- " 10 cu @ surface & erected P & A marker.
- All intervals filled w/ Heavy mud.
Final cleanup shall be made and location levelled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **AREA SUPERINTENDENT** DATE **MAY 2 1973**

APPROVED BY **1- DIV**
1- SUSP
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

0+ 2. NMOCC. H
1- DIV
1- SUSP
1- RRY