

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103 **MAR 13 1970**
 Supersedes ~~C-102~~
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator McAlester Fuel Company	8. Farm or Lease Name Brownfield "B"
3. Address of Operator c/o Hobbs Pipe & Supply P O Box 2010 Hobbs, N Mex	9. Well No. 1
4. Location of Well UNIT LETTER G , 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 12S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Southwest Gladiola
15. Elevation (Show whether DF, RT, GR, etc.) 3889' D.F.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Propose to spot 25 sx. cement plug at 5 1/2" casing stub approx. 5200'.
- Propose to spot 25 sx. cement plug at base of 9 5/8" casing shoe @ 4473'.
- Propose to spot 25 sx. cement plug in and out of 9 5/8" casing stub @ 600'.
- Propose to spot 25 sx. cement plug at 13 3/8" casing shoe @ 365'.
- Propose to spot 10 sx. cement plug at surface and erect marker.
- Hole will be loaded with mud laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. Schmeith* TITLE Agent DATE March 6, 1970

APPROVED BY *[Signature]* TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: