

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name WINGERD
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 11
4. Location of Well. UNIT LETTER <u>J</u> <u>2110</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1650</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>24</u> TOWNSHIP <u>12-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat GLADIOLA-WOLFCAMP
15. Elevation (Show whether DF, RT, GR, etc.) <u>3874' G L</u>	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

Physical abandonment operations completed 1-10-68.
Abandoned as follows:

1. Spotted 40 5x cement plug 9785-9550 (Perfs 9575-9692')
2. That & pulled 7" Cog from 4700. 25 st In + out of stab.
3. Spotted 20 5x. In + out of shoe @ 95 7/8" @ 4529.
4. That & pulled 9 7/8" @ 700'. 25 st In + out of stab.
5. 25 st. In + out of 13 3/8" @ 316'.
6. 10 st. @ surface & erect P & A marker.

Final cleanup will be made and ground restored to contour.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

AREA SUPERINTENDENT

SIGNED _____ TITLE _____ DATE 2-26-68

W2 NMDCI-M
1-1500
APPROVED BY John W. Runyan
1-SUSP
CONDITIONS OF APPROVAL, IF ANY:
1-RR1

TITLE _____ DATE _____