

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05045
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Wingerd
8. Well No. 12
9. Pool name or Wildcat Gladiola Wellcamp <i>Gladiola</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3887 KB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Fina Oil & Chemical Company
3. Address of Operator P.O. Box 2990, Midland, TX 79702
4. Well Location Unit Letter <u>0</u> : <u>990</u> Feet From The <u>South</u> Line and <u>1650'</u> Feet From The <u>East</u> Line Section <u>24</u> Township <u>12-S</u> Range <u>37E</u> NMPM <u>Lea</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>
OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:
REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A recompletion to the Wolfcamp was attempted, but was unsuccessful. There were no other potentially productive zones. The wellbore had no further use to the lease and was plugged and abandoned as follows: Set 5 1/2" Alpha CIBP @ 9440'. Dump bail 40' cmt on top of CIBP. Freepoint 5 1/2" csg @ 4860'. Cut csg @ 4860'. Pull 146 jts. 5 1/2" csg (4860') from hole. RIH w/ workstring and tag cmt plug @ 9401' (BLM representative witnessed tag). Pull tbh uphole. Circulate 5 1/2" csg full of 10# gelled mud @ 6900'. Pump 25 sx Class "c" plug w/ 3% CaCl<sub>2</sub>. Pull up to 4909'. Circulate w/ 10# gelled mud and pump 220 sx cmt plug (plug across 8 5/8" shoe and 5 1/2" stub). Was unsuccessful in recovering any 8 5/8" csg. Pump 90 sx cmt @ 360'. Spot cmt inside and outside of 8 5/8" csg and up to 50' to surface. WOC 3 hrs. TAG top of cmt @ 50' (BLM witnessed). Ru vacuum truck, run hose down 8 - 5/8" csg and remove all water off top of cmt plug. Filled 8 - 5/8" csg w/ cmt to within 18" of top of wellhead. WOC until next morning. Dug up wellhead. Cut off wellhead and install 4' PA marker. Cleaned all excess materials off location. Dug up flowline to well and remove it from location. All PA operations completed on 5/4/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Neva Herndon* TITLE Petrotechnical Associate DATE 5/11/93

TYPE OR PRINT NAME Neva Herndon

TELEPHONE NO. (915) 688-0600

(This space for State Use)

APPROVED BY *Jack Griffin* TITLE OIL & GAS INSPECTOR DATE JUN 17 1993

CONDITIONS OF APPROVAL, IF ANY:

*JR*  
5/11/93