NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103 Supersedes Old
54474 55		C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.5.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5, State Oil & Gas Lease No.
(DO NOT USE THIS FOR	SUNDRY NOTICES AND REPORTS ON WELLS IM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
OIL GAS WELL WELL	X OTHER-	
2. Name of Operator		9. Farm or Lease Name
TOM L. INGR	RAM	Foster
3. Address of Operator		ા Well No.
P. O. Box	1757 - Roswell, New Mexico 88201	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER P	990 FEET FROM THE South LINE AND 330 FEET FROM	Gladiola Wolfcamp
UNIT LETTER	FEET FROM THE LINE AND FEET FROM	
THE East	INE, SECTION 27 TOWNSHIP 12S RANGE 37E NMPM.	
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3889' GR	Lea
16.		
	Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTIC	CE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	_
	OTHER	
OTHER	ОТНЕН	
	mpleted Operations (Clearly state all pertinent details, and give pertinent dates, including	s estimated date of starting any proposed
17, Describe Proposed or Co		s estimated date of starting any proposed
17, Describe Proposed or Co	mpleted Operations (Clearly state all pertinent details, and give pertinent dates, including	
17, Describe Proposed or Co		
17, Describe Proposed or Co	mpleted Operations (Clearly state all pertinent details, and give pertinent dates, including Set castiron plug @ 9030' and cemented with 2 sacks	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17, Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Co	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8". Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs. Plugged and Abandoned on 12/31/71. Will notify when location is ready for inspection.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut 5½'' casing @ 6000' - Unable to pull. Cut 5½'' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs. Plugged and Abandoned on 12/31/71. Will notify when location is ready for inspection.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut $5\frac{1}{2}$ ' casing @ 6000' - Unable to pull. Cut $5\frac{1}{2}$ ' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8". Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs. Plugged and Abandoned on 12/31/71. Will notify when location is ready for inspection.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut 5½'' casing @ 6000' - Unable to pull. Cut 5½'' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs. Plugged and Abandoned on 12/31/71. Will notify when location is ready for inspection.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut 5½'' casing @ 6000' - Unable to pull. Cut 5½'' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs. Plugged and Abandoned on 12/31/71. Will notify when location is ready for inspection.	
17. Describe Proposed or Cowork) SEE RULE 1703.	Set castiron plug @ 9030' and cemented with 2 sacks Cut 5½'' casing @ 6000' - Unable to pull. Cut 5½'' casing @ 5000' and pulled. Placed 25 sack plug in and out of casing @ 5000'. Placed 25 sack plug @ 4502' at base of 9 5/8''. Placed 10 sack plug @ surface with marker. Mud laiden fluid used between plugs. Plugged and Abandoned on 12/31/71. Will notify when location is ready for inspection.	

MEDEIVED

JAN 8 1.72

OL CHISTRIATION COMA.