

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MOSS OFFICE OCC

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	X	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Dallas, Texas

(Place)

April 19, 1954

(Date)

Gentlemen:

B. M. Lowe

Following is a Notice of Intention to do certain work as described below at the

H. S. Moss et al

(Company or Operator)

Well No. 1 in NW

(Unit)

NE 1/4, 34, T. 12S, R. 37E, NMPM, Wildcat Pool

(40-acre Subdivision)

Lea

County.

FULL DETAILS OF PROPOSED PLAN OF WORK

We wish to plug the above well immediately. It was drilled to P.D. 12,987'. Tested through perforation 12283-12290; 12295-12328. This zone abandoned and retainer was set @ 12216 and cement dumped on top of the retainer. Hole was filled with mud and the zones from 9722-42; 9750-9760, 9770-84, tested. We wish to put a cement plug (20 sacks) or retainer at 9650, fill hole with mud and attempt to pull the 5 1/2" casing. (Top of cement is approximately 7750'.) We will then fill the hole with mud and put a cement plug (20 sacks) in the bottom of the 8-5/8" casing (top cement approximately 1400'). ^{attempting to pull 8-5/8" then} filling the hole with mud and putting cement plug 20 sacks in bottom of the surface pipe 341' and a cement plug approximately 5 sacks in top of surface pipe, fill the cellar and put in regulation marker 4" dia set in concrete 4' above ground level. The offset operators were notified according to your regulations.

Approved, 1954, 19.....
Except as follows:

Place 20 sx plug in across bottom of 8-5/8" casing & 4493. After pulling 8-5/8" csg. place plug across pipe @ approx. 1400'.

Approved
OIL CONSERVATION COMMISSION

By

Title

H. S. MOSS

Company or Operator

By JOHN M. LITTLE, JR.

Supt.

Position.....
Send Communications regarding well to:

Name

Address 1503 FIRST NATIONAL BANK BLDG