

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-05068
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Midhurst
Well No. 2
Pool name or Wildcat Gladiola Penn. Southwest
Well Location Unit Letter <u>F</u> : <u>1880</u> Feet From The <u>North</u> Line and <u>1880</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>12S</u> Range <u>37E</u> NMPM <u>Lea</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

Name of Operator
Nearburg Producing Company

Address of Operator
3300 N A St. Bldg 2, Suite 120, Midland, TX. 79706

Well Location Unit Letter <u>F</u> : <u>1880</u> Feet From The <u>North</u> Line and <u>1880</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>12S</u> Range <u>37E</u> NMPM <u>Lea</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.)

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug # 1 2-14-01 Dump Bail 35' of cement on top of existing CIBP @ 9715' WOC & Tag @ 9680'

Plug # 2 2-14-01 Set CIBP @ 9500'

Plug # 3 2-15-01 Circulate well with mud laden fluid. Spot 25 sks of C cement @ 9500'. Tag @ 9300'

Plug # 4 2-19-01 Perf. @ 5920'. Squeezed 50 sks of cement. Tagged @ 5585'

2-20-01 Cut & pulled 4550' of 5 1/2" casing.

Plug # 5 2-19-01 Spot 40 sks of cement @ 4600'. Tag @ 4430'

Plug # 6 2-21-01 Spot 35 sks of cement @ 460'. Tag @ 340'

Plug # 7 2-21-01 Spot 10 sk surface plug 30' to surface

2-22-01 Cut off wellhead and anchors 3' BGL Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Jack Shelton TITLE Agent DATE 02-23-01

TYPE OR PRINT NAME Jack Shelton TELEPHONE NO. 915-523-5155

(This space for State Use)

APPROVED BY Billy E. Lueker TITLE COMPLIANCE OFFICER DATE Feb 21 2001

CONDITIONS OF APPROVAL IF ANY: