

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

30-025-05082

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name H. L. Lowe "C"
9. Well No. 1
10. Field and Pool, or Wildcat King
12. County Lea

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Salt Water Disposal Well
2. Name of Operator Cabot Corporation
3. Address of Operator P. O. Box 1101, Pampa, Texas 79065
4. Location of Well UNIT LETTER O, 1650 FEET FROM THE East LINE AND 467 FEET FROM THE South LINE, SECTION 26 TOWNSHIP 13S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3853 Gr.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

## SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

## 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cabot began plugging operations on 4-7-75 and completed same on 4-11-75. We have listed below our manner of plugging.

- Hole was loaded with 9.1 mud laden fluid.
- Plug #1: 15 sacks cement on top of cast iron bridge plug at 9350', top of cement 9250'.
- Cut and pull 5½" casing at 4770'.
- Plug #2: 75 sacks cement from 4820-4550'.
- Cut and pull 8-5/8" casing at 215'.
- Plug #3: 60 sacks cement from 260-160'.
- Plug #4: 10 sacks cement from 12-0'.
- Installed a 4' x 4' steel marker in concrete with name and location engraved on marker.
- The pits have been filled, location levelled and cleaned of junk.

## 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Kay Woodbridge</u>	TITLE <u>Agent</u>	DATE <u>9-5-75</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE <u>JAN 22 1976</u>
CONDITIONS OF APPROVAL, IF ANY:		