

Submit 3 Copies
to Appropriate
District Office

STATE OF NEW MEXICO
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 888210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO	30-025-05093
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	J L Reed
8. Well No.	3
9. Pool name or Wildcat	King SWD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/> OTHER SWD <input type="checkbox"/>
2. Name of Operator	Paladin Energy Corp.
3. Address of Operator	10290 Monroe Drive, Suite 301, Dallas, TX 75229
4 Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line <u>1980</u> Feet from The <u>East</u> Line Section <u>35</u> Township <u>13S</u> Range <u>37E</u> NMPM <u>Lea</u> County Elevation (Show whether DF, RKB, RT, GR, etc)	

Check Appropriate Box to Indicate Nature of Notice, Report, Or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	<input type="checkbox"/>	REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	COMMENCE DRLG OPNS.	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	CSG TST & CMT JOB	<input type="checkbox"/>
OTHER	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103

MIRU Pulling Unit

Pull 3-1/2" tubing and packer @ 4500' out of hole. GBIH with work string.
Spot 100' Plug from 5,900' to 6,000' (+,-). WOC, Tag cement and varify top.
Spot 200 ft. cement plug from 4483' - 4683' across 8-5/8" shoe @ 4,583'. WOC. Tag cement and varify top.
Spot 100' cement plug inside 8-5/8" casing from 1,900' to 2,000'.
Spot 100' cement plug inside 8-5/8" from 310 - 410'.
Spot surface plug from 0 to 60'. Backfill and clear location.
Place dry hole marker and move off location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Plaisance TITLE V. P., Production DATE June 21, 2002

TYPE OR PRINT NAME David Plaisance TELEPHONE NO. 214-654-0132
(This space for State Use)

APPROVED BY _____ DATE JUL 2 2002

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY
DATE
FIELD REPRESENTATIVE
THE BOARD OF LAND AND MINERAL INVESTMENT
24 HOURS PRIOR TO THE BOARDING OF
FOR INFORMATION FOR THE BOARD
TO BE REVIEWED.

5
C