

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 37-025-05103
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Johnny
8. Well No. 1
9. Pool name or Wildcat King SWD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD
2. Name of Operator Paladin Energy Corp.
3. Address of Operator 10290 Monroe Drive, Suite 301, Dallas, TX 75229
4. Well Location Unit Leader D : 660' Feet From The North Line and 660' Feet From The West Line Section 1 Township 14S Range 37E NMMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1101.

- 11-11-02 Move rig and cmt. equipment in.
- 11-12-02 Rig up unit, RIH w/ tbg. set down @ 4660', spot 60 sx cmt. @ 4660'.  
(Okayed by Billy Prichard w/ O.C.D. @ 4:50 PM TX time) WOC until next day.
- 11-13-02 Tag cmt. plug @ 4495', mud up hole, test csg. @ 600 PSI, held okay. Spot 30 sx cmt. @ 2000', POOH spot 30 sx cmt. @ 421' WOC.
- 11-14-02 Tag cmt. plug @ 301', spot 15 sx cmt. to surface (60-0').  
Cut off wellhead, install dry hole marker, clean location. RDMO.

Approved as to Plugging of the Well Bore.  
Liability under bond is retained until  
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 11-19-02  
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 915-530-0907

(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY  
GARY W. WINK

DATE

CONDITIONS OF APPROVAL, IF ANY:

EXECUTIVE / STAFF MANAGER