

# OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

Sept. 18, 1957

The Atlantic Refining Co.  
Box 871  
Midland, Tex.

Gentlemen:

An inspection of the location for your J. L. Reed No. 1 in Unit D of Section 1, T-14-S, R-37-E has been made by Mr. Eric Engbrecht, Oil & Gas Inspector. He found that the cellar had caved in beside the 4" marker. It is his recommendation that enough cement to give a solid foundation be placed in the void at the top.

Please advise this office when this has been done so that a final inspection may be made. It will also be necessary for you to submit Form C-105, Well Record, before approval can be made of your Report of Final Plugging.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery  
Proration Manager

mc

C  
O  
P  
Y

NOPTMMOO HCTAYEENP, NO

2000 年 12 月 15 日

[illegible]

100

1. The first of these is the fact that the  
2. Government has been unable to secure the  
3. necessary funds to carry out its policy.  
4. This is due to the fact that the  
5. Government has been unable to secure the  
6. necessary funds to carry out its policy.  
7. This is due to the fact that the  
8. Government has been unable to secure the  
9. necessary funds to carry out its policy.  
10. This is due to the fact that the  
11. Government has been unable to secure the  
12. necessary funds to carry out its policy.

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the situation.

100-2761

10. *Chrysomelidae* (10 spp.)

1945