

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name Central Drinkard Unit
2. Name of Operator Chevron U.S.A. Inc.		8. Farm or Lease Name
3. Address of Operator P.O. Box 670, Hobbs, NM 88240		9. Well No. 128
4. Location of Well UNIT LETTER <u>B</u> <u>810</u> FEET FROM THE <u>North</u> LINE AND <u>2180</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3459		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER <u>sqz, perf,</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 4-13-88 thru 4-21-88 TD: 7644 PB: 6700

POOH w/ production equipment. Pmp tbq cap. Set cmt retainer, test tbq to 3000psi, load and test annulus to 500psi, estab. inj rate of 1 1/2 bpm at 900psi, mix and pump 200sx Cl H cmt, sqz perfs 6469-6520 w/2300psi. Rev out 4bbls. Estb. circ, drlg 3'cmt, drill cmt rtnr 6374-6408 (cmt green), WOC 18 hrs. Drlg cmt 6408 - 6565, c/o to 6700. Displace hole w/ CBW. Perf 6535-6548-6556-6561-6573-6587 w/4" guns loaded 2 SPF, 180° phase, Acidize perfs 6585 - 6587, w/ 4100 gallons 15% NEFE HCL. Swab. TIH, tag sand at 6501'. Wash sand 6510 0 6700, PBTD. RIH w/ 2 7/8" , ND BOP, NU WH, TAC at 6422, SN at 6553', 2 7/8" J-55, 8rd tbq at 6589'. Space out, hang on, Test pmp, ok. Turn over to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Klein TITLE Staff Drlg. Engr. DATE May 5, 1988

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE MAY 6 - 1988