

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
ANGEL	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
GLADIOLA WOLFCAMP	
12. County	
LEA	

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFRAC OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - M (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
SKELTON OIL COMPANY
3. Address of Operator
BOX 840 Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER K 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 5 TOWNSHIP 12 RANGE 38 NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3879 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-25-76 Commence clean out operations.
Installed BOP - Started Drilling cement plug - found - much junk in hole -

11-4-76 Ran wash pipe - wash over tubing

12-7-76 Ram Guns perforated - 9425, 26, 27 - 9451, 52, 53 - 9472, 73, 74

12-8-76 Halliburton acidized - tubing leaking

12-14-76 Ran cement retainer - squeeze well - drill out retainer

12-17-76 Perforated 12 perfs, 2 shots per foot 9472-9478. Acidized and swabbed well.

12-29-76 Ran pump and rods, start pumping

1-3-77 Well down

1-27-77 Pull pump - start swabbing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Office Manager DATE 1-28-77

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 2 1977

CIL COMMUNICATION COMM.
HOBBS, N. M.